UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM-081208
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill o to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
	Hospah
1. oil gas uell other	9. WELL NO.
2. NAME OF OPERATOR	65
Tenneco Oil Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Low Hospah
P. O. Box 3249, Englewood, CO 80155	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	~ · · · · · · · · · · · · · · · · · · ·
below.)	Sec. 12, T17N R9W
AT SURFACE: 1418' FNL 2769' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	McKinley NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	7002 gr.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES	
ABANDON* LI LIJS. QLOLOGROAL SER	Way I have the second of the s
(other) FARMINGTON, N. M	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stating including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	directionally drilled, give subsurface locations and
1/30/82 - MIRUSU.	
2/3/82 - RIH w/tbg and 8-5/8" fullbore pkr to t	top of retainer. Set pkr and PT
retainer to 1,000 psi - test good. Tstd BS to	500 psi - test good. POOH w/tbg an
pkr. RIH w/tbg and stringer for retainer. Stu	ing into retainer and established
rate @ 1-1/2 BPM and 1500 psi. Mixed 50 sxs Cl	lass B cmt. Pmpd 3 bbls cmt below
retainer when perfs squeezed off. Pld out of r	retainer and reverse circ'd clean.
POOH w/tbg and stinger.	
2/4/82 - RIH w/tbg to 1593' and spotted 126 gal	ls 15% MCA over perfs. POOH w/tbg.
Perf'd Upper Hospah w/4" csg gun w/4 JSPF as fo	
93' (22' - 88 holes). POOH w/wash tool. Acidi	

18. I hereby certify that the foregoing is true and correct

2/5/82 - RIH w/tbg and SN. Landed tbg @ 1595'.

TITLE Production Analyst DATE (This space for Federal or State office use)

and put on production.

Subsurface Safety Valve: Manu. and Type ___

acid.

DATE _

Swbd acid load back.

ACCEPTED FOR RECORD

Set @

RIH w/rods

*See Instructions on Reverse Side

FEB 17 1982