Form 3160-5 (Juste 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM	APPR	OVED	
Budget Bun	eau No.	1004-01	35
Expires:	March	31, 1993	

		Expires:	March	31.1	993
5.	Lease	Designat	on and	Sen	al No.

1.100	12235	

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

6. If Indian, Allonee or Tribe Name

Use "APPLICATION FOR PERMIT— for such proposals	
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well Oil Well Well Other	8. Well Name and No.
2. Name of Operator	South Hospah Unit #66
Citation Oil & Gas Corp.	9. API Well No.
3. Address and Telephone No.	
8223 Willow Place South Ste 250 Houston, Texas 77070 (713)469-	966410. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	5. Hospah URL: 1.
	11. County or Parish, State
1646' FNL & 2667' FEL Sec. 12, 17N, 9W	McKinley County, NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, RE	PORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTI	ON
Notice of Intent DEGEVE X Abandonment	Change of Plans New Construction
	Non-Routine Fracturing
Subsequent Reposition MAR1 8 1993 Plugging Back Casing Repair	Water Shut-Off
The second secon	Conversion to Injection
OIL CON. DIV X other amendment to plug	Dispose Water
DIST. 3 abandonment procedu	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of s	
give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	

HOSPAH #66 P&A Procedure

- 1. TIH w/open-end 2 7/8" tbg to retainer at 1619'. Spot 61 sx Class B cmt w/2% Cacl2. Pull up to \pm 1200', reverse circulate until clean. WOC 2 kgs. 5
- 2. Tag TOC. Spot 8.4 ppg mud from TOC to ± 580'. Pull tbg to 580'. Pump 70 sx Class B neat (volume will fill csg and tbg to surface). LD tbg. Top of csg when Trjt remains in hole. LD jt.
- 3. Cut off csg and weld on plate with 4" X 4' marker post. Clean location.

: 20 M

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Signed Si	_{Tide} <u>Production</u> Regula	atory Supv	Date	3-8-93
(This space for Federal or State office use)				
Approved by Conditions of approval, if any:	Title	A	PPA(VED
			MAR 15	1993

*See instruction on Reverse Side

112

IN REPLY REFER TO (019)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

intention to Abandon

Well: 66 South Hospuh Unit

CONDITIONS OF APPROVAL

. Plugging operations authorized are subject to the attached "General equirements for Permanent Abandonment of Wells on Federal Leases."

t least 24 hours before the plugging operations commence (505) 599-8907

- . Blowout prevention equipment is required.
- The following modifications to your plugging program are to be made (when pplicable):

The plugging mud is to have a minimum Viscosity of 40 sec/gt.

ffice Hours: 7:45 a.m. to 4:30 p.m.