

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LC 2779	
7. Unit Agreement Name	
8. Farm or Lease Name STATE	
9. Well No. 10	
10. Field and Pool, or Wildcat CHAPCO WASH MV	
12. County MC KINLEY	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator GEO ENGINEERING INC
3. Address of Operator PO BOX 2966 SANTA FE, NM 87504-2966	4. Location of Well UNIT LETTER B 47 FEET FROM THE N LINE AND 1367 FEET FROM THE E LINE, SECTION 28 TOWNSHIP 20N1 RANGE 9W NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 6415 GR	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

CONDITIONS OF APPROVAL:

- Set bridge plug no more than 50' above perforations (306'-511').
- Load hole with inert fluid.
- Pressure test casing and bridge plug to 100 psi for 15 minutes.
- Cap well. Clean location. Install well sign.
- Notify the Aztec NMOC district office 48 hours in advance of commencement of work.
- Work must commence by June 20, 1986.

RECEIVED
APR 15 1986
OIL CON. DIV.
DIST. 6

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Bill Saw</u>	TITLE <u>PETR ENGR</u>	DATE <u>4-13-86</u>
APPROVED BY <u>Carolyn J. [Signature]</u>	TITLE <u>Field Representative</u>	DATE <u>4-21-86</u>
CONDITIONS OF APPROVAL, IF ANY: See above.		