

GOVERNOR

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

February 5, 1986

Mr. Jim Woods Geo-Engineering, Inc. P.O. Box 1417 Socorro, NM 87801

Re: State # 13, B-28-20N-09W State # 24, B-28-20N-09W State # 29, G-28-20N-09W State # 33, H-28-20N-09W State #100, G-28-20N-09W

Dear Mr. Woods:

The referenced wells have been shut in by our office due to noncompliance of our rules and regulations. NMOCD Rule No. 313, states that tank bottoms shall not be allowed to pollute streams or cause surface damage. If the tank bottoms are removed to surface pits, the pits shall be fenced and the fence shall be kept in good repair. When you have complied with NMOCD Rule No. 313, I will recommend that the referenced wells be returned to production and the transporter will be advised to recommence purchase of products.

Yours truly,

Caroyln J. Taplin

Cawlyn J.

Deputy Oil & Gas Inspector

CJT/di

xc: Prentiss Childs
Arlene Luther
Jeff Taylor
UIC File
Well File
Operator File