

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR WTR OIL COMPANY	8. FARM OR LEASE NAME Federal
3. ADDRESS OF OPERATOR c/o Mark E. Weidler, 415 W. Main, Farmington, N.M. 87401	9. WELL NO. 3412 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 350'FEL, 330'FSL	10. FIELD AND POOL, OR WILDCAT Wildcat
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 9-T18N-R12W N.M.P.M.
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6434	12. COUNTY OR PARISH McKinley
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1/31/81 Drilling at 1867'

2/01/81 Preparing to ream core hole at 2250'.

It is proposed to plug and abandon this well in the following manner:

Surface to 140', 35 sacks
270' to 570', 70 sacks
1110' to 1400', 80 sacks
2050' to 2220', 50 sacks
Set dry hole marker at surface.
Verbal approval received January 26, 1981.

FOR: WTR OIL COMPANY

18. I hereby certify that the foregoing is true and correct

SIGNED EWELL N. WALSH TITLE President, Walsh Engr. & Production Corp. DATE 2/02/81

(This space for additional state office use)

APPROVED BY JAN 3 1981

TITLE

DATE

DIST. ENGR.

*See Instructions on Reverse Side