

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

1 Bruce Anderson
SUBMIT IN TRIPPLICATE
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-013
Expires August 31, 1985

1 File

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug wells in a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Bruce Anderson for Geo Engineering Inc.

3. ADDRESS OF OPERATOR
c/o P.O. Box 208, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1652' FNL & 939' FEL

16. PERMIT NO.

17. ELEVATIONS (Show whether of, to, or, etc.)
6449' GR

5. LEASE IDENTIFICATION AND SERIAL NO.
NM 0254488

6. OF INHER, ALLOTTEE OR TRING NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal "A"

9. WELL NO.
5

10. FIELD AND POOL, OR WILDCAT
Wildcat Blackeye Mv

11. SEC., T., R., M., OR BLM AND
SUBST OR AREA
Sec. 30, T20N, R9W, NMPPM

12. COUNTY OR PARISH
McKinley

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PLUG OR ALTER CASING
MULTIPLE COMPLETION
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Request permission to plug and abandon the subject well as follows:

1. Plan to fill 4½" OD, 9.5#, J-55 casing from P.B.T.D. 1120' to surface with 91 sx (107 cu.ft.) class "B" neat cement.
2. Plan to install permanent dry hole monument.
3. Plan to fill all pits.
4. Plan to clean well location of all equipment, pipe, junk and trash.
5. Plan to restore surface, reseed with prescribed BLM seed mixtures.

8. I hereby certify that the foregoing is true and correct

SIGNED Sherman E. Rugan
Sherman E. Rugan

TITLE Agent

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED
MAY 20 1983
OIL CON. 141
APPROVED BY
AS AMENDED
MAY 23 1988
AREA MANAGER

NMOCG

BUREAU OF LAND MANAGEMENT
1235 La Plata Highway
Farmington, New Mexico 87401

Attachment to Notice of
Intention to Abandon

Re: Permanent Abandonment

Well: Fed "A" #5

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."

2. Mark Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 325-4572.

3. Blowout prevention equipment is required.

4. The following modifications to your plugging program are to be made (when applicable):

* Per 4 1/2" casing @ 50' + circulate cement behind casing to surface.

Office Hours: 7:45 A.M. to 4:30 P.M.