State of New Mexico   Energy, Minerals and Natural Resources   Data Collision   Data Coll	Submit 3 Copies To Appropriate District			,		
Construction   Cons		State of ]	New Mexico	,	<b>.</b>	
### Annual First. Annual First	1625 N. French Dr., Hubbs, NiM 99240				Revised March 25, 1000	
2040 South Pacheco   South Pacheco   Santa Fe, NM 87505   SUNDRY NOTICES AND REPORTS ON WELSO   SUNDRY NOTICES AND REPORTS ON WELSO   SUPERIOR REPORTS ON WELSO   Superior   Sundry Notices   Sundry	811 South First, Artesia NM 88210			WELL API NO 30-031-20	928	
SANTA FE, NM 87505  The SANTA FE, NM 87505  The SANTA FE, NM 87505  SANTA FE, NA SANTA FE, NM 87505  The SANTA FE, NM 87505  SANTA FE, NA SANTA FE, NM 87405  The SANTA FE, NM 87505  The SANTA FE MARKE FINE FE  The ALE SAND FRANCE (23 CUFT FOR ILLIA FOR SANTA FILL SANTA FE MARKE FILL SA	1000 Rio Brazos Rd. Aztro NIA 82410 2040 South Pachage			5. Indicate Typ		
CONDITION   COUNTY NOTICES AND REPORTS ON WELLS	District IV			STATE	STATE TO FEE	
DIFFERNT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  2. Name of Operator P. 0.80X 51 FARMINGTON, NM 87499  3. Address of Operator P. 0.80X 51 FARMINGTON, NM 87499  4. Well Location  Unit Letter B 990 feet from the NORTH line and XXXX 1650 feet from the EAST line and Substitution of the Section 16 Township 20N Range 12W NMPM CountyMcKINLEY  10. Elevation (Show whether DR, RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMPLETION  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMPLETION  OTHER: OTHER COMPLETION CICASING TEST AND CEMENT JOB OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  1st PLUG 2220'-2020' (27cuft- 23sk) TAG PLUG @ 1997'  2nd PLUG 1990'-990' (14cuft- 12sk)  3rd PLUG 150'- SURFACE (23cuft-19sk)  ERECTED DRY HOLE MARKER - RESTORED LOCATION	SUNDRYNOTIC	FS AND REPORTS ON		6. State Oil & LG 9425	Gas Lease No.	
2. Name of Operator R & J ENTERPRISES  3. Address of Operator P.O. BOX 51 FARMINGTON, NM 87499  4. Well Location  Unit Letter B 990 feet from the NORTH line and 1111 1650 feet from the EAST line and 1111 1650 feet from the	DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)  1. Type of Well:	LS TO DRILL OR TO DEEPE TION FOR PERMIT" (FORM	EN OR PLUG BACK TO A (C-101) FOR SUCH	7. Lease Name	or Unit Agreement Name:	
Section   16   10   10   10   10   10   10   10	2. Name of Operator	J Other			OKIE	
4. Well Location  Unit Letter B : 990 feet from the NORTH line and 1888 1650 feet from the EAST in Section 16 Township 20N Range 12W NMPM CountyMcKINLEY  10. Elevation (Show whether DR, RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDON CEMENT JOB  PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB  OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion recompilation.  1st PLUG 2220¹-2020¹ (27cuft- 23sk) TAG PLUG @ 1997¹  2nd PLUG 1990¹-990¹ (14cuft- 12sk)  3rd PLUG 150¹- SURFACE (23cuft-19sk)  ERECTED DRY HOLE MARKER - RESTORED LOCATION	K & J ENTERPRISES	8. Well No. #5	8. Well No. #5			
Unit Letter B : 990 feet from the NORTH line and XXXX 1650 feet from the EAST line and Section 16 Township 20N Range 12W NMPM County Mck INLEY  10. Elevation (Show whether DR, RKB, RT, GR, etc.)  - 6142  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMPLETION CEMENT JOB  OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  1st PLUG 2220'-2020' (27cuft- 23sk) TAG PLUG @ 1997'  2nd PLUG 1090'-990' (14cuft- 12sk)  3rd PLUG 150;- SURFACE (23cuft-19sk)  ERECTED DRY HOLE MARKER - RESTORED LOCATION	P.U.BOX 51 FARMINGTON NM 87400			9. Pool name or	9. Pool name or Wildcat	
Section 16 Township 20N Range 12W NMPM CountyMckINLEY    10. Elevation (Show whether DR, RKB, RT, GR, etc.)	4. Wen Location			NOOEROCK		
Section 16 Township 20N Range 12W NMPM CountyMcKINLEY  10. Elevation (Show whether DR, RKB, RT, GR, etc.)  - 6142  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ALTERING CASING  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CEMENT JOB  OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  1st PLUG 2220'-2020' (27cuft- 23sk) TAG PLUG @ 1997'  2nd PLUG 1090'-990' (14cuft- 12sk)  3rd PLUG 150;- SURFACE (23cuft-19sk)  ERECTED DRY HOLE MARKER - RESTORED LOCATION		990 feet from the NC	ORTH line and	1433 1650 feet fro	om the EAST line	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CEMENT JOB  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  Take the proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion recompilation.  1st PLUG 2220'-2020' (27cuft- 23sk) TAG PLUG @ 1997'  2nd PLUG 1090'-990' (14cuft- 12sk)  3rd PLUG 150'; SURFACE (23cuft-19sk)  ERECTED DRY HOLE MARKER RESTORED LOCATION	10	Township 20N	Range 12W	3/3 (D) (		
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENT COMPLETION COMPLETION CEMENT JOB  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  The proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  1st PLUG 2220'-2020' (27cuft- 23sk) TAG PLUG @ 1997'  2nd PLUG 1090'-990' (14cuft- 12sk)  3rd PLUG 150; SURFACE (23cuft-19sk)  ERECTED DRY HOLE MARKER RESTORED LOCATION		► D:4/				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMPLETION CASING TEST AND CEMENT JOB OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  1st PLUG 2220'-2020' (27cuft- 23sk) TAG PLUG @ 1997'  2nd PLUG 1090'-990' (14cuft- 12sk)  3rd PLUG 150;- SURFACE (23cuft-19sk)  ERECTED DRY HOLE MARKER RESTORED LOCATION	NOTICE OF INTE	ropriate Box to India ENTION TO: PLUG AND ABANDON [	_   SUI	BSEQUENT RF	PORT OF:	
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  OTHER:  Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat or recompilation.  SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  1st PLUG 2220'-2020' (27cuft- 23sk) TAG PLUG @ 1997'  2nd PLUG 1090'-990' (14cuft- 12sk)  3rd PLUG 150;- SURFACE (23cuft-19sk)  ERECTED DRY HOLE MARKER RESTORED LOCATION	TEMPORARILY ABANDON   (	HANGE PLANS [	_	_		
OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  1st PLUG 2220'-2020' (27cuft- 23sk) TAG PLUG @ 1997'  2nd PLUG 1090'-990' (14cuft- 12sk)  3rd PLUG 150;- SURFACE (23cuft-19sk)  ERECTED DRY HOLE MARKER RESTORED LOCATION		MULTIPLE [	CASING TEST A			
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  1st PLUG 2220'-2020' (27cuft- 23sk) TAG PLUG @ 1997'  2nd PLUG 1090'-990' (14cuft- 12sk)  3rd PLUG 150;- SURFACE (23cuft-19sk)  ERECTED DRY HOLE MARKER - RESTORED LOCATION	OTHER:	Г	OTUED.			
2nd PLUG 1090'-990' (14cuft- 12sk)  3rd PLUG 150;- SURFACE (23cuft-19sk)  ERECTED DRY HOLE MARKER - RESTORED LOCATION	<ol> <li>Describe proposed or completed of starting any proposed work). S or recompilation.</li> </ol>	perations. (Clearly state EE RULE 1103. For Mu		give pertinent dates, ch wellbore diagram	including estimated date of proposed completion	
3rd PLUG 150; - SURFACE (23cuft-19sk) ERECTED DRY HOLE MARKER RESTORED LOCATION	1st PLUG 2220'-2020' (	27cuft- 23sk)	TAG PLUG @ 1997	ı		
3rd PLUG 150; - SURFACE (23cuft-19sk) ERECTED DRY HOLE MARKER RESTORED LOCATION	2nd PLUG 1090'-990' (	14cuft- 12sk)			~	
ERECTED DRY HOLE MARKER RESTORED LOCATION				A Comment of the Comm		
		, , , , , , , , , , , , , , , , , , , ,		Nea -		
I hereby certify that the information of the control of the contro	ERECTED DRY HOLE MARKET	RESTORED LOCA	ATION			
I hereby certify that the info/him A				٠ حد ٠	:	
I hereby certify that the into which				,		
I hereby certify that the into-falsion of the						
hereby certify that the information of the company						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	I hereby certify that the information abo	ive is true and complete t	to the best of my knowled	ge and belief.		
SIGNATURE TITLE OWNER DATE 3/14/02	/ 1	. / /			DATE3/14/02	
Type or print name JOHN CUNNINGHAM	Type or print name UJOHN CUNNIN	IGHAM /		. Telenh		
(This space for state use)	•		PENTY CE S OF			
APPPROVED BY		Y E. VILLANUEVA	LTE	U IRSPECTOR, MOT.		