Submit 3 Copies To Appropriate District Office	State of				D : 134 106 10
District I	Energy, Minerals	s and Natu	ral Resources	WELL API NO.	Revised March 25, 19
625 N. French Dr., Hobbs, NM 88240 District II	ON CONCERN		DIVERSION	WEEL ALTHO	30-031-20976
811 South First, Artesia, NM 88210	OIL CONSER			5. Indicate Type	e of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410		outh Pack		STATE	☐ FEE 🖾
District IV 2040 South Pacheco, Santa Fe, NM 87505	Santa r	Fe, NM 87	/303	6. State Oil &	Gas Lease No.
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.) 1. Type of Well: Oil Well Gas Well	ES AND REPORTS CALS TO DRILL OR TO DEILL OR TO DEILL OR TO DEIL TION FOR PERMIT" (FOI	EPEN OR PLI	UG BACK TO A	7. Lease Name of SANTA FE	or Unit Agreement Na PACIFIC
2. Name of Operator ENERDY				8. Well No.	#205
3 Address of Operator	X 502, ALBUQUERQ	NIE NM 9	27103	9. Pool name o	
4. Well Location	A JUZ, ALBOQUERQ	20L, 14141 c	37103	- CHACO WA	ISH WESA VERDE
Unit Letter P:	265 feet from the	SOUT	ΓH line and	445 feet fro	om the <u>EAST</u> lin
Section 21	Township	20N Ra	ange 9W	NMPM	County McKINLE
garatine illustra i quita e il esti, impere expresi esti i se estimata cuti att anatomiste.	10. Elevation (Show	whether D 6423' GR		ic.)	us, worder thereby may display as a control desertions on Arthritis
11. Check Ar	propriate Box to In			Report or Other	Data
			SUE	SEQUENT RE	PORT OF:
NOTICE OF INT		\square	REMEDIAL WOR	RK V	ALTERING CASING
PERFORM REMEDIAL WORK			REMEDIAL WOR		ALTERING CASING PLUG AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDO			RILLING OPNS.	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDOI CHANGE PLANS MULTIPLE COMPLETION		COMMENCE DE CASING TEST A CEMENT JOB OTHER:	RILLING OPNS.	PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDOI CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clear	Thy state all	COMMENCE DE CASING TEST A CEMENT JOB OTHER:	ND	PLUG AND ABANDONMENT tes, including estimated
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe proposed or complet of starting any proposed work). or recompilation.	PLUG AND ABANDOI CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clear SEE RULE 1103. For	ly state all r Multiple (COMMENCE DE CASING TEST A CEMENT JOB OTHER: pertinent details, a Completions: Atta	ND	PLUG AND ABANDONMENT tes, including estimated a of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe proposed or complet of starting any proposed work). or recompilation. WELL BORE WILL BE TRE	PLUG AND ABANDOI CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clear SEE RULE 1103. For	ly state all r Multiple C	COMMENCE DE CASING TEST A CEMENT JOB OTHER: pertinent details, a Completions: Atta	ILLING OPNS	PLUG AND ABANDONMENT tes, including estimated of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe proposed or complet of starting any proposed work). or recompilation.	PLUG AND ABANDOI CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clear SEE RULE 1103. For	ly state all r Multiple C	COMMENCE DE CASING TEST A CEMENT JOB OTHER: pertinent details, a Completions: Atta	ILLING OPNS	PLUG AND ABANDONMENT tes, including estimated a of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe proposed or complet of starting any proposed work). or recompilation. WELL BORE WILL BE TRE WORK WILL COMMENCE	PLUG AND ABANDOI CHANGE PLANS MULTIPLE COMPLETION Red operations. (Clear SEE RULE 1103. For	rly state all r Multiple C	COMMENCE DE CASING TEST A CEMENT JOB OTHER: Pertinent details, a Completions: Attainment Attainment Completion BY DE ER OR EARLY M	IND Indigive pertinent datch wellbore diagram CEMBER 31, 2000	PLUG AND ABANDONMENT tes, including estimated of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe proposed or complet of starting any proposed work). or recompilation. WELL BORE WILL BE TRE WORK WILL COMMENCE	PLUG AND ABANDOI CHANGE PLANS MULTIPLE COMPLETION Red operations. (Clear SEE RULE 1103. For	TO PROD	COMMENCE DE CASING TEST A CEMENT JOB OTHER: Dertinent details, a Completions: Attainment Attainment Completion BY DE ER OR EARLY Note that the completion of	IND Indigive pertinent datch wellbore diagram CEMBER 31, 2000	PLUG AND ABANDONMENT tes, including estimated a of proposed completion OCT 2000
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe proposed or complet of starting any proposed work). or recompilation. WELL BORE WILL BE TRE WORK WILL COMMENCE	PLUG AND ABANDOI CHANGE PLANS MULTIPLE COMPLETION Red operations. (Clear SEE RULE 1103. For	TO PROD F OCTOB	COMMENCE DE CASING TEST A CEMENT JOB OTHER: Pertinent details, a Completions: Attainment Attainment Completion BY DE ER OR EARLY M	and give pertinent darch wellbore diagram CEMBER 31, 2000 IOVEMBER, 2000 dge and belief.	PLUG AND ABANDONMENT tes, including estimated of proposed completion

Conditions of approval, if any: