

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. SF 078360
2. NAME OF OPERATOR Bannon Energy, Inc. c/o Holcomb Oil & Gas, Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 2058, Farmington, NM 87499	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit B 970' FNL and 1850' FEL NMPM	8. FARM OR LEASE NAME Nancy 14
14. PERMIT NO.	9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, G, etc.) 7086' KB	10. FIELD AND POOL, OR WILDCAT Escrito Lybrook <i>Dalling</i>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 14 T23N R7W
	12. COUNTY OR PARISH Rio Arriba
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Nancy 14-1

1. Began plug and abandon operations on 10-6-89.
2. Spot 45 sx Class B cement on CIBP at 5325'.
3. Perforate circulating shots in 4-1/2" casing at 4550', 2512', 2180', 320'.
4. Spot 75 sx Class B at 4600', tag top of cement at 3727' KB.
5. Set retainer at 2412', squeeze perfs at 2512' with 50 sx, left another 5 sx on top of tool.
6. Set retainer at 1400', squeeze perfs at 2180' with 302 sx, left another 5 sx on top of tool.
7. Circulate 130 sx Class "B" cement down 4-1/2" casing, through perfs at 320' and back to surface via 8-5/8" x 4-1/2" annulus.
8. Cut off wellhead, installed P&A marker on 10-24-89.
9. Surface is part of yard and will not be reclaimed until all surface activity is abandoned.

Approved by _____
Special Agent in Charge
Bureau of Land Management

18. I hereby certify that the foregoing is true and correct

SIGNED W. J. Holcomb TITLE Agent, Bannon Energy DATE 10-26-89

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY: _____

*See Instructions on Reverse Side

