

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

WELL RECORD

Mail to District Office, Oil Conservation Commission, to which Form C-101 was sent not later than twenty days after completion of well. Follow instructions in Rules and Regulations of the Commission. Submit in QUINTUPLICATE. If State Land submit 6 Copies

Itadani m.		•					IV , NMPM
						-	County
							South lin
							, 19.59
	-						
	_	•	*				
Elevation above		-		182	The inf	formation given is	to be kept confidential unti
			o	IL SANDS OR Z	ONES		
lo. 1, from	307	5to	3085	No. 4	, from	to)
-							
lo. 3, from		to	······································	No. 6	, from	to)
			IMPO	RTANT WATER	SANDS		
nclude data o	on rate of wat	er inflow and	elevation to which	n water rose in hol	е.		
Vo. 1, from	·····		to			feet	a region of the second of the
						feet.	······································
No. 3, from	•••••		to				, ED
No. 4, from	•••••		to		湖 :	feet.	
				CASING RECO	RD .	No.	and Charles of the Company of the Co
SIZE	WEIGHT PER FOO	NEW C		KIND OF	CUT AND PULLED FROM	PERFORATIONS	
8 5/8=	29#	Used	יועונ				Surface String
1 1/2"	9.5#	Nev	31.391	<u> </u>		3075-3085	0il String
			winne	G AND CEMENT	INC DECORD		
	SIZE OF CASING	WHERE SET	NO. SACES	METHOD USED		MUD	AMOUNT OF MUD USED
SIZE OF	CASING		110	Pump & plu			NEED COLD
HOLE	Q E /Q					4	
	8 5/8	1561 3151	225	Pump & plu		8	

......Depth Cleaned Out.....

RECORD OF DRILL-STEM AND SPECIAL TESTS

If drill-stem or other special tests or deviation surveys were made, submit report on separate sheet and attach hereto

TOOLS USED

							feet to	
				RODUCTION				
t to Produc	ing. 9-	-26	, 19.	59				··· ^
L WELL:	The production	during the first 24 l	nours was		ba	rrels of lic	quid of which	%
							% was se	
					/6 Water	, and	% was se	eaiment. A.
	•	*						
S WELL:	The production	during the first 24 h	nours was	558	M,C.F. pl	lus	·. • • • • • • • • • • • • • • • • • • •	barrels
	liquid Hydrocarl	bon. Shut in Pressur	. TP 822	lbs. CP 822	2#			
noth of Tir	_	8 hrs.						
_								
PLEASE				CONFORMAN	CE WITI	H GEOGI	RAPHICAL SECTION O	-
A h	***	Southeastern New				-	Northwestern New 2896	
•	•••••••••••••••••••••••••••••••••••••••						Ojo Alamo	
							Farmington	
			,,	******************************			Pictured Cliffs. 3075	
7 Rivers		п	-				Menefee	
Queen		т	. Ellenburge	r		т.	Point Lookout	
				•••••			Mancos	•••••
	es			•			Dakota	
	***************************************						Morrison	
		_					Penn	
							3923	

							•	
			FORMA	TION RECO	ORD			
	Thickness				<u> </u>	Thickness		
rom T	in Feet	Forma	tion	From	To		Formation	L
					10	in Feet		
		PE	LFOR AT TONS			in Feet		· · · · · · · · · · · · · · · · · · ·
		e j PE	LFORATIONS			in Feet		
.G.A.C.	I F	PES 3075-3085		3		in Feet		
.G.A.C.	I F	9 6. 3075 -30 85	w/20 jet	3	10	in Feet		
.G.A.C.	I F	9 6. 3075 -30 85		3		in Feet		·
.G.A.C.	I F	9 2. 3075 –30 85 <u>SUD</u>	w/20 jet	3		in Feet		
-28-59 -21-59	Staked Loc Commenced	56. 3075-3085 SUP cation Drlg sperati	w/20 jet	shets.		in Feet		
-28-59 -21-59 -21-59	Staked Loc Commenced Ran 8 5/8	SUP cation Drlg operati	W/20 jet	shets.				
-28-59 -21-59	Staked Loc Commenced Ram 8 5/8: Completed	SUP sation Drlg eperati esg. hole. ID 31	MARY ons (spuc	i date)	an Ind	neti.on	electrical log &	•
-28-59 -21-59 -21-59	Staked Loc Commenced Ram 8 5/8' Completed attempted	SUP sation Drlg eperati esg. hole. ID 31	MARY ons (spuc	i date)	an Ind	netion		
-28-59 -21-59 -21-59 - 2-59 - 3-59	Staked Loc Commenced Ran 8 5/8: Completed attempted Ran kgs es	stion Drlg operation to run Sonie g could not BAR Service,	MARY ons (spuce to be leg hit	i date) imberger r tight place	an Ind	etion	set well into s	hale
-28-59 -21-59 -21-59 - 2-59 - 3-59 - 4-59	Staked Loc Commenced Ram 8 5/8: Completed attempted Ran kgs es section & Released :	stion Drlg eperati esg. hole. TD 31 to run Senie g could not BAR Service,	MARY ons (spud ios. Schl log hit get to be Inc. res	i date) imberger r tight place	an Ind e @ 16 est ci	retion- oi. re, es	set well into a	hale
-28-59 -21-59 -21-59 - 2-59 - 3-59 - 4-59	Staked Loc Commenced Ram 8 5/8° Completed attempted Ran kg* en section & Released : Brlg out	SUP sation Drlg eperati esg. hole. TD 31 to run Senie g could not BMR Service, rig.	MARY ons (spud ios. Schl log hit get to be Inc. res	i date) lumberger r tight place ptten A/x 1 a temp surv	an Ind e 0 16 est ci	retion- oi. re, es	set well into a	hale
-28-59 -21-59 -21-59 - 2-59 - 3-59 - 4-59 - 8-59	Staked Loc Commenced Ram 8 5/8° Completed attempted Ran kg* co section & Released 1 Brig out of Herce sand	stion Drlg eperati cation Drlg eperati cag. hole. TD 31 te run Senie g could not Ber Service, rig. em in kg* te i wtr frae pe	MARY ons (spud ios. Schl log hit get to be Inc. res	i date) lumberger r tight place ptten A/x 1 a temp surv	an Ind e 6 16 est ci	vetion-	N COMMISSION	hale
-28-59 -21-59 -21-59 - 2-59 - 3-59 - 4-59 - 8-59	Staked Loc Commenced Ran 8 5/8° Completed attempted Ran 12° co section & Released of Brig out of Hewce sand	stion Drlg eperati esg. hole. TD 31 te run Senie g could not BMR Service, rig. em in kg* te wtr frae pe	MARY ons (spuce to be less to be	i date) lumberger r tight place ptten A/x 1 a temp surv	an Ind e 6 16 est ci	retion- oi. re, es	N COMMISSION	hale
-28-59 -21-59 -21-59 -2-59 -3-59 -8-59 -8-59 -10-59 -19-59	Staked Loc Commenced Ram 8 5/8: Completed attempted Ran kgs es section & Released : Brig out of Herce sand Ran 1 to Started to SI for Poi	stion Drig eperati esg. hole. TD 31 te run Senie g could not BMR Service, rig. em in kg* te i wtr frae pe	MARY ons (spuce to be less to be	i date) lumberger r tight place ptten A/x 1 a temp surv	an Ind e 6 16 est ci	vetion-	N COMMISSION	hale
-28-59 -21-59 -21-59 -2-59 -3-59 -8-59 -8-59 -10-59 -19-59	Staked Loc Commenced Ram 8 5/8: Completed attempted Ran hgs es section & Released : Brig out of Herce sand Ran lgs ti Started to	stion Drig eperati esg. hole. TD 31 te run Senie g could not BMR Service, rig. em in kg* te i wtr frae pe	MARY ons (spuce to be less to be	i date) lumberger r tight place ptten A/x 1 a temp surv	an Ind e 6 16 est ci	vetion-	N COMMISSION	hale
-28-59 -21-59 -21-59 -2-59 -3-59 -4-59 -8-59 -8-59 -10-59	Staked Loc Commenced Ram 8 5/8: Completed attempted Ran kgs es section & Released : Brig out of Herce sand Ran 1 to Started to SI for Poi	stion Drig eperati esg. hole. TD 31 te run Senie g could not BMR Service, rig. em in kg* te i wtr frae pe	MARY ons (spuce to be less to be	i date) lumberger r tight place ptten A/x 1 a temp surv	an Ind e 6 16 est ci	vetion-	N COMMISSION	hale
-28-59 -21-59 -21-59 -2-59 -3-59 -8-59 -8-59 -10-59 -19-59	Staked Loc Commenced Ram 8 5/8: Completed attempted Ran kgs es section & Released : Brig out of Herce sand Ran 1 to Started to SI for Poi	stion Drig eperati esg. hole. TD 31 te run Senie g could not BMR Service, rig. em in kg* te i wtr frae pe	MARY ons (spuce to be less to be	i date) lumberger r tight place ptten A/x 1 a temp surv	an Ind e 6 16 est ci	vetion-	N COMMISSION	hale
-28-59 -21-59 -21-59 -2-59 -3-59 -8-59 -8-59 -10-59 -19-59	Staked Loc Commenced Ram 8 5/8: Completed attempted Ran kgs es section & Released : Brig out of Herce sand Ran 1 to Started to SI for Poi	stion Drig eperati esg. hole. TD 31 te run Senie g could not BMR Service, rig. em in kg* te i wtr frae pe	MARY ons (spuce to be less to be	i date) lumberger r tight place ptten A/x 1 a temp surv	an Ind e 6 16 est ci	vetion-	N COMMISSION	hale
-28-59 -21-59 -21-59 -2-59 -3-59 -8-59 -8-59 -10-59	Staked Loc Commenced Ram 8 5/8: Completed attempted Ran kgs es section & Released : Brig out of Herce sand Ran 1 to Started to SI for Poi	stion Drig eperati esg. hole. TD 31 te run Senie g could not BMR Service, rig. em in kg* te i wtr frae pe	MARY ons (spuce to be less to be	i date) lumberger r tight place ptten A/x 1 a temp surv	an Ind e 6 16 est ci	vetion-	N COMMISSION	hale
-28-59 -21-59 -21-59 -2-59 -3-59 -8-59 -8-59 -10-59 -19-59	Staked Loc Commenced Ram 8 5/8: Completed attempted Ran kgs es section & Released : Brig out of Herce sand Ran 1 to Started to SI for Poi	stion Drig eperati esg. hole. TD 31 te run Senie g could not BMR Service, rig. em in kg* te i wtr frae pe	w/20 jet MARY Lons (spuce 165. Schl 1 leg hit get to be Inc. res 3105 PHI Ef.	i date) i date) imberger r tight place ottom A/x 1 temp surv	an Inde 6 16 sst ci	vation vation vation	N COMMISSION A logs domes le	hale
-28-59 -21-59 -21-59 -2-59 -3-59 -8-59 -8-59 -10-59 -19-59 -26-59	Staked Loc Commenced Ram 8 5/8° Completed attempted Ran kg* en section & Released : Brig out of Herce sand Ran 1g* th Started to SI for Pot Pot. compl	superation Orlg operation Orlg operation to run Senion g could not HAR Service, rig. on in har to letted.	MARY ONARY ONARY ONARY OS (Spuce OS Schill Log hit get to be Inc. res 3105 PH Ff. p.m.	i date) Lumberger r tight place ptton A/x 1 temp surv	an Inde 6 16 set ci	vetion- o'. re, es, vatio eceive	N COMMISSION R loss Hours by	hale Osg.
-28-59 -21-59 -21-59 -2-59 -3-59 -8-59 -8-59 -10-59 -19-59 -26-59	Staked Loc Commenced Ram 8 5/8° Completed attempted Ran 12° co section & Released : Brig out of Howe sand Ran 12° ti Started to SI for Pot Pet. sempl	superation Orlg operation Orlg operation cage hole. TD 31 to run Senion g could not His Service, rig. of how 6 1;00 attach Separation ATTACH SEPARATION	MARY ONARY ONARY ONARY OS (Spuce OS Schill Log hit get to be Inc. res 3105 PH Ff. p.m.	i date) lumberger r tight place ptten A/x 1 tep surv D. Plice	an Inde 6 16 set ci	vetion- o'. re, es, vatio eceive	N COMMISSION A logs domes le	hale Osg.
-28-59 -21-59 -21-59 -2-59 -3-59 -8-59 -8-59 -10-59 -19-59 -26-59	Staked Loc Commenced Ram 8 5/8° Completed attempted Ran kg* en section & Released : Brig out of Herce sand Ran 1g* th Started to SI for Pot Pot. compl	superation Orlg operation Orlg operation cage hole. TD 31 to run Senion g could not His Service, rig. of how 6 1;00 attach Separation ATTACH SEPARATION	MARY ONARY ONARY ONARY OS (Spuce OS Schill Log hit get to be Inc. res 3105 PH Ff. p.m.	idate) Lumberger r tight place ttop surv B. Pilot i tap surv i tap surv	NAE SPA	vation vation vation deceive	COMMISSION 1088 10872 kg the well and all works	hale Osg.
-28-59 -21-59 -2-59 -3-59 -3-59 -8-59 -8-59 -10-59 -19-59 -26-59	Staked loc Commenced Ram 8 5/8: Completed attempted Ran 12* ca section & Released : Brig out Howe sand Ran 12* th Started to SI for Pot Pot. compl	stion Drlg operation Rese. hole. TD 31 to run Senie g could not BMR Service, rig. in in the to i wtr free per flow 6 1:00 leted. ATTACH SEPAR hat the information able records.	MARY Ons (spuce 165. Schl 165.	i date) Lumberger r tight place otten A/x 1 tesp surv D. Place of IF Addition is a complification is a complification	NAE SPA	CE IS IN	N COMMISSION R loss Hours by	hale Osg.