

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SF-078272-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Campos

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lybrook Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

10-23N-7W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7264 GR

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-9-74⁷³ Set plug at 5239'. Found hole at 4450'
Set Guiberson 4 1/2 packer at 4250 and squeezed with
2% Ca Cl and 113#'s analad-9.

12-10-74⁷³ Drilled approximately 90 feet of cement and tested casing
to 1000#'s for 15 minutes.

12-12-74⁷³ Spotted 500 gallons 7 1/2% acid. Swabbed to 12-15-74

12-15-74⁷³ Spotted 1000 gallons 7 1/2% acid Swabbed to 12-17-74

12-18-74⁷³ Placed well back in operation.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE President

DATE March 18, 1974

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: