


(SUBMIT IN TRIPLICATE)

Land Office **Santa Fe**

Lease No. **SF-078493-A**

Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 2, 19**63**

Yarborough-Federal "B"
Well No. **1** is located **660** ft. from **{N}** line and **530** ft. from **{E}** line of sec. **10**

NW 1/4 of Sec. 10 (1/4 Sec. and Sec. No.)
Undesignated (Field)
23-N (Twp.) **6-W** (Range) **NMPM** (Meridian)
Rio Arriba (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is **6730** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was plugged and abandoned as follows:

Spotted 50 sack cement plug across perforations 5434' to 5524' and 10 sack plug in top of 5 1/2" casing. Interval between plugs was filled with heavy mud. Cut off well head and welded 4" pipe marker in top of 5 1/2" casing.

Completed plugging and cleaned up location 12-30-63.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **TEXACO Inc.**

Address **P. O. Box 810**

Farmington, New Mexico

By *C. P. E.*

Title **District Superintendent**

