SERVATION ONVISION Oi.

P. O. BOX 2986

Form C-102

SANTA FE, NEW MEXICO 87501 Revised 10-1-78 ENERGY AND MINERALS DEPARTMENT All distances must be from he outer boundaries of the Section. Operator 1.0000 Well No. Southern Union Exploration Company Yarborough Fed. Section Township Range Unit Letter County 10 23NRio Arriba Actual Footage Location of Well: 660 feet from the North 53() feet from the Dedicated Acreage: Producing Formation 6730 Gallup Counselor Gallup Acres 1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below. 2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty). 3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling, etc? If answer is "yes!" type of consolidation Yes No If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.)___ No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Division. CERTIFICATION I hereby certify that the information contoined herein is true and complete to the best of my knowledge and belief. 5 3c Position Southern Union Expl. Tigte 12-10-82 I hereby certify that the well location shown on this plat was platted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my knowledge and belief. Date Surveyed Registered Professional Engineer and/or Land Surveyor Certificate No.

26 40