

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. NW 050290

Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Subsequent Report of Cementing Casing</u>

RECEIVED

DEC 18 1961

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

11 December, 1961

Well No. 1 Gov't. Inter. is located 330 ft. from S line and 1980 ft. from W line of sec. 5

SW 1/4 Sec. 5 24 N. 1 E. NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)


Wildcat Rio Arriba New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6982 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- 12-5-61 Spudded well.
- 12-7-61 "rilled 12 1/2" hole to 165' and cemented 8-5/8" 24# J-55 casing at 150' with 60 sacks of cement treated with 2% CaCl<sub>2</sub>.
- 12-8-61 "rilled out 8-5/8" shoe.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Loma-Latitude

Address Box 351

Durango, Colo.

By Clinton White  
Clinton White  
Title Agent