

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER		5. LEASE DESIGNATION AND SERIAL NO. Jicarilla Contract 71
2. NAME OF OPERATOR John E. Schalk		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache
3. ADDRESS OF OPERATOR P. O. Box 2078, Farmington, New Mexico 87401		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790' Fr S. Ln, 1850' Fr E. Ln.		8. FARM OR LEASE NAME Cinco Diablos
14. PERMIT NO.		9. WELL NO. 7
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7430 GR.		10. FIELD AND POOL, OR WILDCAT Ballard
		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10, T-23N, R-4W
		12. COUNTY OR PARISH Rio Arriba
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL


ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 8-9-67. Set 8-5/8" 24# Casing @ 117' in 12-1/4" Hole W/100 Sks Neat, 27 Ca Cl2. WOC 12 Hrs, tested Casing to 500 #. Drilled 7-7/8" Hole to 3170' on 8-13-67, Ran IES and Density Logs. Ran 94 Jts 4-1/2" 9.5 # Casing, Set @ 3170, Cemented W/100 Sks 50:50 Pozmix, 42 Gal and 100 Sks Class A Neat. WOC. Perforated 3053-63 and 3069-88 W/1 Hole/FT. SWF W/40,000 # 20-40 Sand, 40,950 Gals Water W/2 # FR-8/1000 Gals. FBD 2500 #, TP. 1000 - 2000 #, Avg 1300 Rate 44.2 SI 600 #. Dropped 22 balls in 6 Stages. Ran 92 Jts 1-1/2" 2.75# Tubing, landed @ 3054. Well unloaded after 2 days, cleaned, shut in for I. P. Test.



18. I hereby certify that the foregoing is true and correct

SIGNED William H. Hascroft TITLE Office Manager

DATE 8-27-67

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

Instructions


General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685228

8 87-8 51



Specimen to be submitted