Ferm 9-331 (May 1963)	UNITED STATES	SUBMIT IN TRIPLICATES	
	DEPARTMENT OF THE INTER	RIOR verse side)	5. LEASE DESIGNATION AND SERIAL NO.
	GEOLOGICAL SURVEY		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME
			Jicarilla Apache
1.			7. UNIT AGREEMENT NAME
OIL GAS WELL	OTHER Proposed Locatio	าก	
2. NAME OF OPERATOR			8. FARM OR LEASE NAME
Chace Oil Company			Jicarilla 71
3. ADDRESS OF OPERATOR			9. WELL NO.
·			
313 Washington, S.E., Albuquerque, New Mexico 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			6
Sag also enagg 17 holow i			10. FIELD AND POOL, OR WILDCAT
At surface A Unit 330' NL, 330' EL Sec. 10, T-23-N, R-4-W			
			11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
			Sec. 10, T-23-N, R-4
			Sec. 10, 1-25-N, K-4
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) GR 7398		12. COUNTY OR PARISH 13. STATE	
			Rio Arriba N.M.
16.	Check Appropriate Box To Indicate	Nature of Notice, Report, or (Other Data
			UENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE		ALTERING CASING
		FRACTURE TREATMENT	-
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING		ABANDONMENT*	
REPAIR WELL CHANGE PLANS (Other) (NOTE: Report results		s of multiple completion on Well	
(Other) Abn. Lo		Completion or Recomp	oletion Report and Log form.)
17. DESCRIBE PROPOSED OR CO proposed work. If w nent to this work.) *	OMPLETED OPERATIONS (Clearly state all pertine ell is directionally drilled, give subsurface loc	ent details, and give pertinent dates sations and measured and true vertic	s, including estimated date of starting any cal depths for all markers and zones perti-
1			
The above	location, being an uno	orthodox location t	was disallowed by
the State	Commission and will be	abandoned	

*See Instructions on Reverse Side