Ferm 9-331 (May 1963)		UNITED STATEMENT OF THE	E INTERIO	RUBMIT IN TRIP. (Other instruction verse side)		Form approved. Budget Bureau No. 42-R1424 5. LEASE DESIGNATION AND BERIAL NO.
		GEOLOGICAL S				6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)						Jicarilla Apache
1.				· · · · · · · · · · · · · · · · · · ·		7. UNIT AGREEMENT NAME
OIL X GAB WELL	OTHER					8. FARM OR LEASE NAME
2. NAME OF OPERATOR						Jicarilla Joint
Odessa Natural Corporation 3. ADDRESS OF OPERATOR						Venture "KD"
P. O. Box 3908 Odessa, Texas 79760						1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface						10. FIELD AND POOL, OR WILDCAT Chacon Dakota Associated Oil Pool 11. SEC., T., E., M., OE BLK. AND
990'FSL, 800'FEL 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)						SURVEY OR AREA
						Sec. 4-T23N-R3W
						N.M.P.M. 12. COUNTY OR PARISH 13. STATE
		7296'GL,	7309'DF	, 7310'KB		Rio Arriba N.M.
16.	Charle 4				ort, or C	
Circuit, ippropriate Desired						DENT REPORT OF:
				THE PROPERTY OF THE PROPERTY O		REPAIRING WELL
TEST WATER SHUT	T-OFF	PULL OR ALTER CASIS MULTIPLE COMPLETE		WATER SHUT-OFF FRACTURE TREATM	ENT -	ALTERING CASING
FRACTURE TREAT SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACID	I	ABANDONMENT*
REPAIR WELL		CHANGE PLANS		(Other) Perf	orate	and Test X
(Other)				Completion	or Recompl	of multiple completion on Well letion Report and Log form.)
17. DESCRIBE PROPOSED proposed work. nent to this work	If well is direct	PERATIONS (Clearly stationally drilled, give s	ate all pertinent subsurface locatio	details, and give perting its and measured and t	nent dates, crue vertica	including estimated date of starting an al depths for all markers and zones per
8-25-77 P	BTD 7670	1				
with 250 g no gas, no	allons l oil. S	5% MCA. Sw et retainer	ab test at 7600	interval, re	ecove: ze pe:	per foot. Acidize ring formation water rforations with 50 •
					Į [*]	
					1	No. 1
					ř	•
					9.	variable of the second of the
					Š.	
						The same construction of
18. I hereby certified SIGNED F.WC	ellu	Well rrect	Pre	esident, Wal Production C	sh En	gineering DATE 9-8-77
(This space for F						
ADDDATED DV			TITLE			C FDIDY F I
APPROVED BY CONDITIONS OF	APPROVAL, I	F ANY:			44	5 1 V E

*See Instructions on Reverse Side