

Federal Building
701 Camino del Rio
Durango, Colorado 81301

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

May 23, 1979

Jack A. Cole
P. O. Box 191
Farmington, New Mexico 87401

Dear Mr. Cole:

Field inspections indicate that Well No. 6 Apache Hills, located in section 17, T. 23 N., R. 3 W., NMPM, on Jicarilla Contract No. 396 was not drilled at the location of the environmental inspection conducted September 18, 1978. The survey stake at the environmental inspection and the Application for Permit to Drill showed the location to be 990 feet from the north and 1850 feet from the west lines of section 17. Subsequent inspections indicate that the well was drilled 200-300 feet south of the staked location and that it may now be an unorthodox gas well.

Pursuant to Title 30 CFR 221.7, 221.57, and 221.58, you are given thirty (30) days from receipt of this letter to file six copies of a plat showing a survey subsequent to May 1, 1979. Failure to comply with this requirement will subject you to assessment of liquidated damages pursuant to 30 CFR 221.54 (a), (c), and (j).

Sincerely yours,

(Orig. Sgd.) C. A. BARRICK
Carl A. Barrick
Acting District Engineer

cc: NMOCC Aztec



i.

A circular ink stamp from the National Bureau of Standards. The text "National Bureau of Standards" is curved along the top inner edge, and "Gaithersburg, Md. 20899" is curved along the bottom inner edge. The center of the stamp contains the date "JUN 1980" and the number "100-100000".

[illegible]