## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

		Budget Bureau No. 42-R1424
	5.	LEASE SF 078362
	6.	IF INDIAN, ALLOTTEE OR TRIBE NAME
nt	7.	UNIT AGREEMENT NAME
	8.	FARM OR LEASE NAME Grace Federal 12
	9.	WELL NO.
)2	10.	FIELD OR WILDCAT NAME Lybrook
7	11.	SEC., T., R., M., OR BLK. AND SURVEY OR AREA
	l	Sec 12, T23N-R7W

SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME Grace Federal 12
1. oil gas well other	9. WELL NO.
2. NAME OF OPERATOR	- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
GRACE PETROLEUM CORPORATION	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR CO 80202	
3 Park Central =200, 1515 Arapahoe, Denver,	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Sec 12, T23N-R7W
AT TOP RECO INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Rio Arriba Co New Mexico
	_ 14. API NO.
<ol><li>CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA</li></ol>	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7055 Ungraded
EST WATER SHUT-OFF	
RACTURE TREAT	
HOOT OR ACIDIZE	
EPAIR WELL  ULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
NULTIPLE COMPLETE	change on Form 9-550.)
CHANGE ZONES	
MININGE ZUNES	
BANDON*	
MBANDON* Other) Report on rig activities	
BANDON* other) Report on rig activities	directionally drilled, give subsurface locations and
BANDON* other) Report on rig activities  7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertinent.	directionally drilled, give subsurface locations and
BANDON* other) Report on rig activities  7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertinents.	directionally drilled, give subsurface locations and
BANDON* other) Report on rig activities  7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertinended.	directionally drilled, give subsurface locations and
BANDON* Other) Report on rig activities  7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is demeasured and true vertical depths for all markers and zones pertined 6/10/80 5140' 6/11/80 5390'	directionally drilled, give subsurface locations and
BANDON* other) Report on rig activities  7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is demeasured and true vertical depths for all markers and zones pertinent 6/10/80 5140' 6/11/80 5390' 6/13/80 5700'	directionally drilled, give subsurface locations and
BANDON* other) Report on rig activities  7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertinent 6/10/80 5140' 6/11/80 5390' 6/13/80 5700' 6/14/80 Fishing	directionally drilled, give subsurface locations and
BANDON* other) Report on rig activities  7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is demeasured and true vertical depths for all markers and zones pertinent 6/10/80 5140' 6/11/80 5390' 6/13/80 5700' 6/14/80 Fishing 7/12/80 Perf. 7/13/80 Frac. Test BP to 3500#. 7/14/80 Frac.	directionally drilled, give subsurface locations and
ABANDON* Other) Report on rig activities  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is demeasured and true vertical depths for all markers and zones pertined  6/10/80 5140' 6/11/80 5390' 6/13/80 5700' 6/14/80 Fishing 7/12/80 Perf. 7/13/80 Frac. Test BP to 3500#. 7/14/80 Frac. 7/16/80 PBTD 5706'	directionally drilled, give subsurface locations and
ABANDON* Other) Report on rig activities  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is demeasured and true vertical depths for all markers and zones pertinent 6/10/80 5140' 6/11/80 5390' 6/13/80 5700' 6/14/80 Fishing 7/12/80 Perf. 7/13/80 Frac. Test BP to 3500#. 7/14/80 Frac. 7/16/80 PBTD 5706' 7/22/80 Swab.	directionally drilled, give subsurface locations and
### Application of the control of th	directionally drilled, give subsurface locations and nt to this work.)*
ABANDON* Other) Report on rig activities  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is demeasured and true vertical depths for all markers and zones pertinent 6/10/80 5140' 6/11/80 5390' 6/13/80 5700' 6/14/80 Fishing 7/12/80 Perf. 7/13/80 Frac. Test BP to 3500#. 7/14/80 Frac. 7/16/80 PBTD 5706' 7/22/80 Swab.	directionally drilled, give subsurface locations and nt to this work.)*
ABANDON* other) Report on rig activities  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is domeasured and true vertical depths for all markers and zones pertinent 6/10/80 5140' 6/11/80 5390' 6/13/80 5700' 6/14/80 Fishing 7/12/80 Perf. 7/13/80 Frac. Test BP to 3500#. 7/14/80 Frac. 7/16/80 PBTD 5706' 7/22/80 Swab.	directionally drilled, give subsurface locations and nt to this work.)*
ABANDON* Other) Report on rig activities  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is discussed and true vertical depths for all markers and zones pertinent of the following state of the following state of the following and true vertical depths for all markers and zones pertinent of the following state of	directionally drilled, give subsurface locations and nt to this work.)*
ABANDON* Other) Report on rig activities  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is discussed and true vertical depths for all markers and zones pertinent of the following of the following state of starting any proposed work. If well is discussed and true vertical depths for all markers and zones pertinent of the following state of the following stat	directionally drilled, give subsurface locations and nt to this work.)*
ABANDON* (other) Report on rig activities  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent 6/10/80 5140' 6/11/80 5390' 6/13/80 5700' 6/14/80 Fishing 7/12/80 Perf. 7/13/80 Frac. Test BP to 3500#. 7/14/80 Frac. 7/16/80 PBTD 5706' 7/22/80 Swab.	directionally drilled, give subsurface locations and nt to this work.)*
ABANDON* Jother) Report on rig activities  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertined  6/10/80 5140' 6/11/80 5390' 6/13/80 5700' 6/14/80 Fishing 7/12/80 Perf. 7/13/80 Frac. Test BP to 3500#. 7/14/80 Frac. 7/16/80 PBTD 5706' 7/22/80 Swab. 7/29/80 Swab. 84 BF.	directionally drilled, give subsurface locations and nt to this work.)*  Set @Ft.

AUG 12 1980