Commission

☐ Final Abandonment Notice

## UNITED STATE: DEPARTMENT OF THE INTERIOF BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No N.M. 33036

## 6. If Indian, Allottee or Tribe Name

Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

| Use "APPLICATION FOR  |                                   |  |
|---|-----------------------------------|--|
| SUBMIT IN TRIPLICATE  |                                   | 7. If Unit or CA, Agreement Designation  |
| Type of Well  Other  Name of Operator  Global Production S.W.   |                                   | 8. Well Name and No. Skipper #1  9. API Well No.   |
| 20 I N. 34th Ave. Suite 2 Hattiesburg, Mi. Location of Well (Footage, Sec. J. R. M. of Syrver Description) Unit D 495 FNL, 825 FWL  Sec 5 T24N, RIE Rio Arriba Co. N.M. |                                   | 10. Field and Pool, or Exploratory Area East Puerto Chiqueto  11. County or Parish, State Sec 5 T24N R1E Rio Arriba Co. N.M. |
| CHECK APPROPRIATE BOX   | s) TO INDICATE NATURE OF NOTICE F | REPORT, OR OTHER DATA  |
| TYPE OF SUBMISSION  | TYPE OF A                         |  |
| Notice of Intent  | Abandonment Recompletion          | Change of Plans  New Construction  |
| Subsequent Report   | Plugging Back Casing Repair       | Non-Routine Fracturing Water Shut-Off  |
|   | T Carrier                         | Conversion to Injection  |


13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated cate of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to plug and abandon, as follows;

Pump cement as deep as we can get approx. 3600'to 3'000'
casing set at 3210, fill from 3000 to 250 with 91b gel,

Spot cement plug 250' to 150' fill 150 to 50' with 9 lb gel.

spot 50' cement plug at surface. Erect dry hole marker, and
restore surface.



OIL CON. DIV.

| ٠.  | DIST. 3   |  |
|---|---|--|
| 4 Thereby certify that the foregoing is true and correct Signed Trackal Production Sw.  | Tille Mach Reynaldis agent  | Date <u>6-1-93</u>                             |
| (This space for federal or State office use) (Original Signed) HECTOR A. VILLALOBOS  Approved by Conditions of approval of ar | Title FIRST MANAGER   | Date FEB 23 1994                               |
| S. Se so (00) makes it a crime for any person knowingly represents one or to any matter within its jurisdicti-                | is and willfully to make to any department or agency of the United Stat | es any false, fictitious or fraudulent stateme |
|   | "See Instruction on Reverse Sic   |  |