Form 3160-5 (November 1983) (Formerly 9-331)	UNITED STATES DEPARTMENT OF THE INTE		5. LEASE DESIGNATION AND SERIAL NO.
C110	BUREAU OF LAND MANAGEME		Jicarilla Tribal 396 6. IF INDIAN, ALLOTTER OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)			Jicarilla Apache
WELL WELL  2. NAME OF OPERATOR	OTHER		S. FARM OR LEASE WAMP
Amoco Production Company			Jicarilla Tribal 396
3. ADDRESS OF OPERATOR			9. WELL NO.
501 Airport Drive, Farmington, NM 87401  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)			5
At surface			West Lindrith GP-DK
1650, LST X 1820, LMT			11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA
		OCT 15 1984	NE/SW Sec. 8, T23N, R3W
14, PERMIT NO.	15. ELEVATIONS (Show whether	OF LAND MANAGEMENT	12. COUNTY OR PARISH 18. STATE
	7455' GR	WINDS BEDOUGH AREA	Rio Arriba NM
16.	Check Appropriate Box To Indicate	Nature of Notice Report or C	
MOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OF	PCLL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL X
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIES	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)(Note: Report results	of multiple completion on Well
17. DESCRIBE PROPOSED OR proposed work. If nent to this work.)	COMPLETED OPERATIONS (Clearly state all pertin well is directionally drilled, give subsurface lo	Completion or Recompleted details, and give pertinent dates, cations and measured and true vertices	of multiple completion on Well letion Report and Log form.) including estimated date of starting any il depths for all markers and zones perti-
Perforated s	I rigged up service unit on squeeze holes at 3610', 4 jsp: retainer at 3435' and squee, 7% Halad 9, 2% $_{ m a}^{ m Cl}_{ m 2}$ . Drift 3435'-3610'. Pressure teste	f, .44" in diameter, fo ezed 3435'-3610' with 1	or a total of 4 holes.
Landed 2-7/8	3" tubing at 7444' and releas	sed the rig on 9/20/84.	•
	مر مه يد		
			JAMI 7 905
	r Siegnia da Bye and correct	ministrative Superviso	r 10/16/01
	J. C	ministrative oupervisor	TOPED FOR RECORD
(This space for Federal	i or State office use)		Thomas
APPROVED BYCONDITIONS OF APP	ROVAL, IF ANY:		OCT 2 1984

\*See Instructions on Reverse Side NMOCC

FARMINGIÚN RESOURCE AREA