



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401

TAKE
PRIDE IN
AMERICA

IN REPLY REFER TO:

NM-23050 (WC)
3162.3-1 (019)

RECEIVED
OCT 23 1991
OIL CON. DIV.
DIST. 3

OCT. 22 1991

Bannon Energy, Inc
c/o Daggett and Chenualt
Attention: Bob Larson
3539 East 30th, Suite 7B
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- ✓ 1. 6 Federal 6, sec. 6, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease NM-23050.
- ✓ 2. 3 Lybrook Federal 24, sec. 24, T. 24 N., R. 7 W., Rio Arriba Co.,
NM, Lease NM-83502.
- ✓ 3. 4 Federal 31, sec. 31, T. 24 N., R. 7 W., Rio Arriba Co., NM,
Lease NM-33005.
- ✓ 4. 6 Federal 13, sec. 13, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease SF-078360.
- ✓ 5. 17 Lybrook South, sec. 13, T. 23 N., R. 7 W., Rio Arriba Co., NM, -- Fed 13 #8
Lease SF-078360.
- ✓ 6. 18 Lybrook South, sec. 14, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease SF-078360.
- ✓ 7. 19 Lybrook South, sec. 14, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease SF-078360.
- ✓ 8. 20 Lybrook South, sec. 14, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease SF-078360.
- ✓ 9. 21 Lybrook South, sec. 14, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease SF-078360.
- ✓ 10. 23 Lybrook South, sec. 18, T. 23 N., R. 6 W., Rio Arriba Co., NM,
Lease SF-078360.
- ✓ 11. 24 Lybrook South, sec. 19, T. 23 N., R. 6 W., Sandoval Co., NM,
Lease SF-078360.
- ✓ 12. 25 Lybrook South, sec. 19, T. 23 N., R. 6 W., Sandoval Co., NM,
Lease SF-078360.
- ✓ 13. 26 Lybrook South, sec. 19, T. 23 N., R. 6 W., Sandoval Co., NM,
Lease SF-078360.

ABANDONED LOCATION

14. 27 Lybrook South, sec. 19, T. 23 N., R. 6 W., Sandoval Co., NM,
Lease SF-078360.

15. 28 Lybrook South, sec. 19, T. 23 N., R. 6 W., Sandoval Co., NM,
Lease SF-078360.

16. 33 Lybrook South, sec. 14, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease SF-078360.

As discussed with Bob Larson, a representative of your company on October 16, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

16 Enclosures

cc:
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

Lybrook Gal. Co. RA S 6	T 23N R 7W U D Oper. Bannon Energy, Inc.	Les. Federal 6	No. 6 ✓
DevFrk Gal. Co. RA S 24	T 24N R 07W U B Oper. Bannon Energy, Inc.	Les. Lybrook Federal 24	No. 3 ✓
Lybrook Gal. Co. RA S 31	T 24N R 07W U A Oper. Bannon Energy, Inc.	Les. Federal 31	No. 4 ✓
Lybrook Gal. Co. RA S 13	T 23N R 07W U N Oper. Bannon Energy, Inc.	Les. Federal 13	No. 6 ✓
Lybrook Gal. Co. RA S 13	T 23N R 07W U P Oper. Bannon Energy, Inc.	Les. Federal 13	No. 8 ✓
Lybrook Gal. Co. RA S 14	T 23N R 07W U K Oper. Bannon Energy, Inc.	Les. Federal 14	No. 5 ✓
Lybrook Gal. Co. RA S 14	T 23N R 07W U L Oper. Bannon Energy, Inc.	Les. Federal 14	No. 7 ✓
Lybrook Gal. Co. RA S 14	T 23N R 07W U M Oper. Bannon Energy, Inc.	Les. Federal 14	No. 6 ✓
Lybrook Gal. Co. RA S 14	T 23N R 07W U N Oper. Bannon Energy, Inc.	Les. Federal 14	No. 8 ✓
Lybrook Gal. Co. RA S 14	T 23N R 07W U P Oper. Bannon Energy, Inc.	Les. Federal 14	No. 10 ✓
Lybrook Gal. Co. RA S 18	T 23N R 06W U L Oper. Bannon Energy, Inc.	Les. Federal 18	No. 4
Lybrook Gal. Co. SA S 19	T 23N R 06W U D Oper. Bannon Energy, Inc.	Les. Federal 19	No. 6 ✓
Lybrook Gal. Co. SA S 19	T 23N R 06W U L Oper. Bannon Energy, Inc.	Les. Federal 19	No. 10 ✓
Lybrook Gal. Co. SA S 19	T 23N R 06W U N Oper. Bannon Energy, Inc.	Les. Federal 19	No. 15 ✓
Lybrook Gal. Co. SA S 19	T 23N R 06W U P Oper. Bannon Energy, Inc.	Les. Federal 19	No. 17 ✓
Lybrook Gal. Co. SA S 19	T 23N R 06W U H Oper. Bannon Energy, Inc.	Les. Federal 19	No. 9 ✓

- N-18-23N-06W — Fed. 18 # 7 —

F

30-039-24942

010-01-90

F. Loc. 672/S; 1980/W Elev. 7011 GL Spd. _____ Comp. _____ TD _____ PB _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas _____
 I.P. _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS		NTD		Well Log		TEST DATA							
Ojo Alamo		C - 103		Plat		Schd.	PC	Q	PW	PD	D	Ref.No.	
Kirtland		C - 104		Electric Log									
Fruitland				C - 122									
Pictured Cliffs		Ditr		Dfo									
Chacra		Datr		Dac									
Cliff House													
Menefee													
Point Lookout													
Mancos													
Gallup													
Greenhorn													
Dakota													
Entrada													
		Acres						40					

P
o
o

Lybrook Gal Co. RA S 18 T 23N R 06W U N Oper. Bannon Energy, Inc. Lse. Federal 18

No. 7

Federal 18 #7

N-18-23N-06W

BANNON ENERGY, INC.