

Jicarilla Tribal Con. 47 #12 L-11-23N-04W

CHACE OIL CO., INC.

J

30-039-25028

11-27-90

F. Loc. 2185/S; 680/W

Elev. 7508 GL

Spd.

Comp.

TD

PB

Cu. ft.

Cu. ft.

Cu. ft.

Sx. Pr.

@

W

Sx.

I.

@

T Gas

Casing S.  
Csg. Perf.

@

W

Sx.

Int.

@

W

Prod. Stim.

T  
R  
A  
N  
S

Grav. 1st Del. Gas

1st Del. Oil

BO/D

MCF/D After

Hrs.

SICP

PSI After

Days GOR

TOPS		NI/TD	Well Log	TEST DATA								Ref. No.
Ojo Alamo		C-103	Plat X	Schd.	PC	Q	PW	PD	D			
Kirtland		C-104	Electric Log									
Fruitland			C-122									
Pictured Cliffs		Ditr	Dfa									
Chacra		Dotr	Dac									
Cliff House												
Menefee												
Point Lookout												
Mancos												
Gallup												
Greenhorn												
Dakota												
Entrada												
			Acres 40									

P

o

S. Lindrith

Gal. Dak. Co. RA S 11

T 23N R 04W U L Oper. Chace Oil Co., Inc.

Lse. Jic. Tribal Cont. 47 No. 12



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
Farmington Resource Area  
1235 Laplata Highway  
Farmington, New Mexico 87401



IS REPLY REFER TO:  
Jicarilla Contract 47 (WC)  
3162.3-1.0 (019)

JAN 30 1992

**RECEIVED**  
JAN 31 1992  
OIL CON. DIV  
DIST. 2

Chace Oil Company, Inc.  
313 Washington, S.E.  
Albuquerque, NM 87108

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

1. No. 12 Jicarilla Tribal Contract 47, Section 11, T. 23 N., R. 4 W.,  
Rio Arriba County, New Mexico
2. No. 21 Jicarilla Tribal Contract 47, Section 11, T. 23 N., R. 4 W.,  
Rio Arriba County, New Mexico

As discussed with Charlotte McClanahan of your company on January 17, 1992, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

John L. Keller  
Chief, Branch of Mineral Resources

2 Enclosures

cc:  
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410  
BIA, Jicarilla Agency, P.O. Box 167, Dulce, NM 87528

**ABANDONED LOCATION**