



DIRECTOR
JOE D. RAMEY

OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS RD. - AZTEC

87410
LAND COMMISSIONER
PHIL R. LUCERO



STATE GEOLOGIST
EMERY C. ARNOLD

December 21, 1977

Mr. Joe Morrow
P. O. Box 1406
Farmington, New Mexico 87401

Re: West & McIntosh
Rollins Dodgen #2
D-28-18N-3W

Dear Mr. Morrow:

Please advise us by telephone at least 24 hours in advance of your field operations as set out in Order R-5555.

Yours very truly,

A. R. Kendrick
A. R. Kendrick
Supervisor, District #3

Attachments: 9-331, Intention to P & A

xc with Attachments: O.C.C., Santa Fe

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR
Joe Morrow - Mc Intosh + West
3. ADDRESS OF OPERATOR
Box 1406, Farmington N.M.
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒
(other) ☐

- ☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE
N.M. 088979-B
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
D 10662
8. FARM OR LEASE NAME
Federal
9. WELL NO.
Rollins + Dodgen #2
10. FIELD OR WILDCAT NAME
San Luis
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 28 T18N R3W
12. COUNTY OR PARISH
Sandoval
13. STATE
N.M.
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

*Plug from 450 to 500 ft.
Fill with mud from 30 to 450 ft.
Plug from 0 to 30 ft.
Put dry hole marker up and clean location.*

Subsurface Safety Valve: Manu. and Type

Set @

18. I hereby certify that the foregoing is true and correct

SIGNED

Joe Morrow

TITLE

operator

DATE

11-23-77

APPROVED

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL

DEC 19 1977

CARL A. BARRICK
ACTING DISTRICT ENGINEER *See Instructions on Reverse Side

