

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

N0215257

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Federal Lease

7. UNIT AGREEMENT NAME

None

8. FARM OR LEASE NAME

Benn-McKay

9. WELL NO.

#2-3 Benn-McKay

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 3T19N, R1W,

NMPH

12. COUNTY OR PARISH 13. STATE

Sandoval

New Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER Wildcat	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
2. NAME OF OPERATOR Benn-McKay	16. U.S.G.S., Nov. 3, 1964 7028 Gr. 7031.5 KB
3. ADDRESS OF OPERATOR Horace F. McKay, Jr.	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 800 Loma Linda Place, S.E., Albuquerque, New Mex. 1190 fsl, 990 fel, Sec. 3T19N, R1W	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☒REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to run 2 7/8 casing to total depth and cement to surface. Will test well by perforation of sands zones.

Plan to do work by January 15, 1965.

2 7/8 to 1751 with 160 sacks.

Perforated Dakota from 1674-1676.

Squeeze Dakota with 15 sacks.

Perforate Gallup and test by swabbing

1183-1206

1352-1362

1142-1152

1294-1300

1102-1110

1064-1074

976- 984

570- 580

Called U.S.G.S.

RECEIVED

NOV 2 1965

OIL CON. COM.
DIST. 3

RECEIVED

NOV 1 1965

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNATURE

TITLE

Operator

DATE

October 25, 1965

(This space for Federal or State bond use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.