

(SUBMIT IN TRIPLICATE)

Indian Agency Dallas, N. M.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Contract No. 172

Allottee _____

Lease No. _____

2			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL <input checked="" type="checkbox"/>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 18, 1961

Florilla-
Well N. 1/4 Sec. 22 is located 800 ft. from N line and 800 ft. from W line of sec. 22

N. 1/4 Sec. 22 (1/4 Sec. and Sec. No.) T22N (Twp.) R4E (Range) N.M.P.M. (Meridian)
Wildcat (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 8000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is intended to plug and abandon this well in the following manner:

- Run a cement plug from total depth (8300') to 8100'.
- Run a cement plug from 8000' to 8100'.
- Run a cement plug from 4800' to 4100'.
- Run a cement plug from 1800' to 1700'.
- Run a cement plug from 12' to surface.

Place a 10' four inch steel pipe marker in cement at surface leaving 4' above ground level with a sign indicating Name, and location of well.

Clean and level location.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Motor Drilling Co.

Address 1700 Glenarm Place

Denver 2, Colorado

By George H. Lenters

Title Exploration Manager

