Form 9-331 . \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	UNITED STATES	SUBMIT IN TRIPLICATE	Form approved. Budget Bureau No. 42-R1424.
(May 1963)/ \. \ \ \ \	PARTMENT OF THE INTE	RIOR (Other instructions on received)	5. LEASE DESIGNATION AND SERIAL NO.
- P. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	GEOLOGICAL SURVEY	- OFILE	6. IF INDIAN, ALLOTTEE OR TRIBE HAME
(Do not use this form f	NOTICES AND REPORTS or proposals to drill or to deepen or plu APPLICATION FOR PERMIT—" for such	ng baok og å different reservoir.	Jicarica
1. OIL GAS WELL WELL	OTHER	OCT 20 1970	7. UNIT AGREEMENT NAME
NAME OF OPERATOR	MINING CORP.	OIL CON. COM.	8. FARM OR LEASE NAME
1/2/4000			9. WELL NO.
	ORPUS CHRISTI, TEXA		10. FIRLD AND POOL, OR WILDCAT
4. LOCATION OF WELL (Report I See also space 17 below.) At surface 1030 454	_ 1030 FEL SEC 2		WILDERT
TZAH R3	N, SANDOVAL CO	NEW MEXICO	11. SEC., T., R., M., OR BLK. AND SUBVEY OR AREA SEC E9 TESH R3W
			12. COUNTY OF PARISH 13. STATE
14. PERMIT NO.	15. ELEVATIONS (Show whethe	er DF, RT, GR, etc.)	SANDOVAL AM.
		N. (N. C. D. and an	
	heck Appropriate Box To Indicate		EQUENT REPORT OF:
NOTICE	OF INTENTION TO:	r	REPAIRING WELL
TEST WATER SHUT-OFF	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	ALTERING CASING
FRACTURE TREAT SHOOT OR ACIDIZE	ABANDON®	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)	lts of multiple completion on Well
(Other)		Completion or Recor	mpletion Report and Log form.)
proposed work. If well	is directionally drilled, give subsurface	locations and measured and true ver	
This w	ell has been abn	ndoned progged	Deceose 67
Mon Commerc	io/ production.	In the tollows.	ng monner.
10-1-70	10-2-70 RAM	7318 ft they in	well, squage
	perfs 6972 -	7316 W/ 60 81 cen	ent, left top of play
	@ 6900'. Lay a		
,	. (2 6 700 . 747 2	1 -1"0 :	at to be so con
10-6-70 / 10.	8-10 Determine	The CHEINES Tree	, pt. +0 52 G 500
•	Perforated 2 hold	er & 3100 Squee	38 W30 W CEMENT
	Loft top of con	ment inside Cos.	ing @ 3050
10-1-70	Perforated 2 hotes	e 500', Squere	W/ 50 by Coment
70-7-70	1 ft to of come	of nordo Cosing C	alm!
	LOFF FOR OT COME	I down the "alog"	Anale
	Pump 30 St Cemen	nt down 5/5"-10%"	
	Set PAA marker	, w/10 5x Sorface	Plug.
10 10 - 30	along location	& move equipmen	→
10-10-76	Char 1000 1111	d mood difference	
18. I hereby certify that the fo	oregoing true and correct	0 1C 0	
SIGNED	asses TITLE	Acont for Operator for	DATE 64/5,(970
(This space for Federal or	NIGHT VINCE UST/	= 1, s	
APPROVED BY	TITLE _		DATE TO BE TO SERVICE OF THE PROPERTY OF THE P