ioo XEX	CODY XERO	X-PRO
083X)	COPT XERO	хсьо сову
:	UNITED STATES SUBMIT IN TRIPLICATE (May 1963) DEPARTMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESCONATION AND SERIAL NO. NM-0772-14
	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME
•	OIL CAS OTHER Dry Hole 2. NAME OF OPERATOR Harry L. Bigbee	8. FARM OR LEASE NAME Fedorel
•	3. ADDRESS OF OPERATOR 1012 Tierra Drive Santa Fo, N.M. 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)	9. WELL NO. 1-33 10. FIELD AND POOL, OR WILDCAT
	At surface 1980' FSL 660" FWL Sec 33 T19N RE RIW	Wildeat 11. SEC, T. E., M., ON BLE. AND SCEVEY OR AREA Sec 33 TION RIW
	16. Check Appropriate Box To Indicate Nature of Notice, Report, or C	12. COUNTY OR PARIDU 13. STATE Sendovel N.M.
	NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL NOTICE OF INTENTION TO: PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* SHOOTING OR ACIDIZING (Other)	BEPAIRING WELL ALTERING CASING ABANDONMENT* of multiple completion on Well stion Report and Log form.)
·	(Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical near to this work.) Plan to plug from: 2400-2678 1090-1400 65-300	
	with 180 sacks cement as verbally approved by USGS Farmington marker and clean up location.	
	(RIUL, 23,966 com.)	FEB 21: 1966 GEOLOGICAL SURV