

Conditions Of Approval For Abandonment

Gola #5 Well

1. The well bore will be filled with 26 sacks of cement or the amount necessary to ensure that well bore is filled top to bottom with Class B cement.
2. Prior to filling the well bore with cement, all water will be removed from the well bore to prevent contamination of the cement.

RECEIVED
MAY 17 1993
OIL CON. DIV
DIST. 3