UNITED STATES

UNITED STATES DEPARTMENT OF THE	NTERIOR	5. LEASE NM-38576 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
GEOLOGICAL SUR		7. UNIT AGREEMENT NAME	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or plug back to a different deservoir. Use Form 9–331–C for 41441 ptdpposals-)			
on not use this form for proposals to difficulties ervoir. Use Form 9-331-C for allel phiposals.)		8. FARM OR LEASE NAME	
1. oil gas		9. WELL NO. Un-named Wtr. Well	
NAME OF OPERATOR Gary-Williams Oil Producer	Ned . Inc. c/o Dollar	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR P.O. Box 399 Aztec. NM 87	(Agent)	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOCATION below.)	N CLEARLY. See space 17		
AT SURFACE: 1980 FNL & 1980 AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	' FEL Sec. 17-20N- R3W	12. COUNTY OR PARISH 13. STATE Sandoval NM 14. API NO.	
L6. CHECK APPROPRIATE BOX TO INDIC REPORT, OR OTHER DATA	ATE NATURE OF NOTICE,	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6816 RDB	
WEGOES! I SW THE SE	SEQUENT REPORT OF:	0010 NDB	
TEST WATER SHUT-OFF UFFACTURE TREAT			
SHOOT OR ACIDIZE		(NOTE: Report results of multiple completion or zone change on Form 9-330.)	
PULL OR ALTER CASING [] MULTIPLE COMPLETE []			
CHANGE ZONES ABANDON* Request for Wtr well			
(Other)		the action of details, and give pertinent dates.	
including estimated date or starting at measured and true vertical depths for a	all markers and zones pertine	ate all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)*	
		andoned well, Pan American "C" n May 1967 to with the intent to lling of oil wells in the surround	ling
	ה ה		
	, N.		
	A	APR 3 0 1984	
	OIL	CON. DIV.	
		DIST. 3	
Subsurface Safety Valve: Manu. and Type		Set (iii)	
18. I hereby certify that the foregoing is true.	ue and correct Agent	APPROVED84	
SIGNED 1. Jun	(This space for Federal or State		
APPROVED BY	TITLE	DATE	
CONDITIONS OF APPROVAL, IF ANY:	,	APR 27 1984	
•	Nmocc	Danny Otherha	
	*See Instructions on Rever	FARMINGTON RESOURCE AREA	