## P. O. How 1809 Durango, Colorado 81301

September 4, 1969

Mr. Donald Burton Box 37 Lindrith, New Mexico 87029

Deer Mr. Burton:

This is to advise that on September 3, 1969, I inspected the Benjamin Elenbogen No. 1 and No. 2 wells located respectively in secs. 30 and 32, T. 23 N. R. 4 W., Sandoval County, New Mexico, on Jicarilla lesse Contract No. 415.

I found that the No. I well was not in acceptable condition for approval of the abandonment because the marker had not been solidly embedded in cement. The abandonment of the No. 2 well was approved on this date.

Please advise this office when the marker at the No. 1 well has been cemented.

Sincerely yours,

(Orig. Sgd.) J. W. LONG

Jerry W. Long District Engineer

cc: Benjamin Elenbogen 4100 Montview Blvd. Denver, Colo., 80207

Roswell NMOCC, Aztec, N. M.L File

JWLong:mka



SEP RECS OIL CON. DOM. V DIST. 3