Oil / Gas / Mining

Geological Consultant 900 Bank of New Mexico Building Albuquerque, New Mexico 87101

January 14, 1971

Office: Phone 243-0665 Home: Phone 255-9749

Mr. Emery Arnold, District Supervisor New Mexico Oil Conservation Commission 1000 Rio Brazos Road Aztec, New Mexico 87410

Re: Refiners Petroleum Corp.
Cuba Union No. 2 well

Dear Mr. Arnold:

In compliance with Rule Nc. 111 of the New Mexico Oil Conservation Commission, straight hole deviation tests were made on the Refiners Petroleum Corp. No. 2 Cuba Union well located 990' from the north line and 990' from the east line in Section 26 of Township 22 North, Range 3 West, NMPM, Sandoval County, New Mexico, as follows:

1-1/4°	@	712'	1/40	@	3670'
30 / '	@	1208	3/40	@	39731
1-1/2°	@	1713'	3/40	@	4298 •
$1-1/2^{\circ}$	@	1874'	1/2	@	45961
$1-3/4^{\circ}$	@	2369	1/4°	@	5037
1-1/2°	@	28441	10	@	5535 <b>'</b>
$\frac{1}{10} \frac{1}{2}$	@	2975	ı°	@	60581
10'	@	35921			

The total depth of this well is 7064'

Sincerely,

TAL D DEDUCE

VAL R. REESE

STATE OF NEW MEXICO : COUNTY OF BERNALILLO :

Subscribed and sworn before me this 14th day of January, 1971.

Notary Public

My commission expires 9-25-73.