Oil/Gas/Mining

Val R. REESE, C.P.G.

Geological Consultant 900 Bank of New Mexico Building Albuquerque, New Mexico 87101

March 13, 1972

Office: Phone 243-0665 Home: Phone 255-9749

Mr. Emery C. Arnold, District Supervisor New Mexico Oil Conservation Commission 1000 Rio Brazos Road Aztec, New Mexico 87410

Re: Fluid Power Pump Company
No. 2 Fluid Power Pump well
Section 15, Township 19 North,
Range 3 West, N.M.P.M., Sandoval
County, New Mexico

Dear Mr. Arnold:

The No. 2 Fluid Power Pump well, located 2310' from the north line and 330' from the east line in Section 15, Township 19 North, Range 3 West, N.M.P.M., Sandoval County, New Mexico, was drilled to a total depth of 5300' and the following vertical deviations, Totco Surveys, were taken from the drilling log:

THE TOE.	
210'	1/2°
849'	$1/2^{0}$
13381	1-1/4°
1850 <b>'</b>	1 0
23691	1/2°
25421	1/2
32831	3/4°
40291	$1-1/4^{\circ}$
4654'	1-1/40

MAP ... MAP ..

I certify that the above surveys are true and correct information from the drilling log in regard to vertical hole deviations on the No. 2 Fluid Power Pump well.

VAL R. REESE, Consulting Geologist

STATE OF NEW MEXICO : COUNTY OF BERNALILLO :

Subscribed and sworn to before me this 13th day of March, 1972.

Notary Public

My commission expires 9-25-73.