_			D.D. 15 a.s.	
NO. OF COPIES RECEIVED	3		PRIVATE	A STATE OF THE PARTY OF THE PAR
DISTRIBUTION				27 TEORING CAINS HAS SAN
SANTA FE	171			supersedes ()[d
FILE	171		NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
U.S.G.S.	+			2.00cmve 1-1-05
LAND OFFICE	1 1	\neg		5a. Indicate Type of Lease
OPERATOR	171			State Fee X
	1 1			5. State Oil & Gas Lease No.
	SLIN	IDP	Y NOTICES AND REPORTS ON WELLS ON FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
(DO NOT USE THIS FO	RM FOR	PROF	POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	MIIIIIIII
1.			FORM C-101) FOR SUCH PROPOSALS.)	
WELL WELL	1 1		OTHER- Well P & A'd	7. Unit Agreement Name
2. Name of Operator				
Shell Oil Co	8. Farm or Lease Name			
	Santa Fe			
1700 Broadwa	9. Well No.			
Location of Well	1			
UNIT : ETTER		3.50	0.04	10. Field and Pool, or Wildcat
OWN CELLER		<u> </u>	0.06 FEET FROM THE SOUTH LINE AND 1070.32 FEET FROM	Cactus Area (WC)
THE West			18 TOWNSHIP 13N RANGE 3E NMPM.	miniminini
LII	NE, SEC	TION	TOWNSHIP 13N RANGE 3E	
	777	77		
		///	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
6.	7777	771	5733 GL, 5753 KB	\ \alpha \ \cdot \ \cdot \ \land \ \la
(Check	: A p	propriate Box To Indicate Nature of Notice, Report or Oth	20120181
NOTICE	EOF	INT	ENTION TO:	er Data
			SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK			PLUG AND ABANDON REMEDIAL WORK	
EMPORARILY ABANDON				ALTERING CASING
PULL OR ALTER CASING			CHANGE PLANS	PLUG AND ABANDONMENT
			CHANGE PLANS CASING TEST AND CEMENT JQB	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

On 8-23, began plugging well as follows:

Ran DP openended to 9550 and cmtd w/100 sx reg cmt w/0.3% D-13R from 9550-9350 (Plug #1)

Set second plug at 7750-7500 w/125 sx reg cmt w/0.2% D-13R. Set third plug at 7050-6850 w/100 sx cmt. Iaid down DP and WOC 10½ hrs. Cut off 9 5/8" Cameron csghd. Welded 9 5/8" csg stub onto csg, extending 2' above GL, and welded 1/2" plate in top of 2" collar. Screwed 2" bullplug in collar. Welded Shell marker at top of 9 5/8" below plate. Filled cellar to GL. Turned well over to State.

18. I hereby certify that the information above is true and complete	
SIGNED	DIST. 3 DIST. 3 DIST. 3 DIST. 3 DIST. 3
CONDITIONS OF APPROVAL, IF ANY:	SUPERVISOR DIST. #3