DATE \_

	115040	TMENT OF THE INT	EDIOD (Other instructions on re-	Budget Bureau Nb 42-R1424.  5. LEASE DESIGNATION AND SERIAL NO.
	DELAN	GEOLOGICAL SURVEY		Jic. Cont. 440
	CULIDAY NO	<del></del>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
		OTICES AND REPORT	Dug back to a different reservoir.	
(150 not us	Use "APPL	Jicarilla Apache		
1. on rong	GAS [7]			7. UNIT AGREEMENT NAME
WELL A	WELL OTHER	L		
2. NAME OF OPERATOR Union Oil Company of California				8. FARM OR LEASE NAME Jicarilla "C"
3. ADDRESS OF OPERATOR				9. WELL NO.
P. O. Box 2620 - Casper, Wyoming 82601				1 (0-32)
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*				10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface				Undesignated
	660' FSL 8		11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA	
				SURVEY OR AREA
				Sec. 32, T.22N., R.5W.
14. PERMIT NO.		15. ELEVATIONS (Show wheth		12. COUNTY OR PARISH 13. STATE
		7271	1' GR	Sandoval New Mexico
16.	Chack	Appropriate Box To Indicat	te Nature of Notice, Report, or O	Other Data
		• •		
	NOTICE OF INT	TENTION 10.	SUBSEQU	ENT REPORT OF:
TEST WATER S	SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TRE	[ <del></del> ]	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACH	DIZE	ABANDON*	SHOOTING OR ACIDIZING (Other) Supplement	tary Well History
REPAIR WELL (Other)	نـــا	CHANGE PLANS	(Note: Report results	of multiple completion on Well etion Report and Log form.)
proposed wo	ork. If well is dire	OPERATIONS (Clearly state all pertectionally drilled, give subsurface	tinent details, and give pertinent dates, locations and measured and true vertical	including estimated date of starting any l depths for all markers and zones perti-
proposed wo nent to this to	to 3945.	Attempted to run DST	tinent details, and give pertinent dates, locations and measured and true vertica  I #2 in Point Lookout For Ray Induction and FDC Log	rmation. Packer seat
proposed wo nent to this to	to 3945.	Attempted to run DST	Fig. 20 and Fig. 2	rmation. Packer seat gs. Drilling. Incomplete
Drilled failed.	to 3945. A	Attempted to run DST	The second and true vertical first second and true vertical first second and for the first second and first second and for the first second and first seco	rmation. Packer seat gs. Drilling. Incomplete
Drilled failed.	to 3945. A Drilled to	Attempted to run DST 4315. Ran Gamma F	The second and true vertical first second and true vertical first second and for the first second and first second and for the first second and first seco	rmation. Packer seat gs. Drilling. Incomplete

TITLE \_

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_\_CONDITIONS OF APPROVAL, IF ANY: