

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-B1426.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0349515

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use APPLICATION FOR PERMIT— for such proposals.)

1. OIL ☒ GAS ☐ WELL ☐ WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME N.A.
2. NAME OF OPERATOR Michael P. Grace	8. FARM OR LEASE NAME Sandy #1
3. ADDRESS OF OPERATOR P. O. Box 1418, Carlsbad, New Mexico	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly, and in accordance with any State requirements.* See also space 17 below.) At surface Sec. 21, T12N., R3W., NMPM Sandoval Co., New Mexico 1980 feet west of east line, 330 North of South Line	10. FIELD AND POOL, OR WILDCAT Wildcat
14. PERMIT NO.	15. ELEVATIONS (Show whether OF, RT, GR, etc.)
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21, T12N., R3W., NMPM
	12. COUNTY OR PARISH Sandoval
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) Complete as water well ☒PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well will be plugged and abandoned as per USGS request with 20 sacks cement plugs at 700--800' and 225'--325'. The well will then be completed for fresh water production in Westwater sands between 121' and 220'.
8 5/8" surface casing cemented @ 103'. WESTWATER fresh water sands @ 120-130, 151-186, 186-210.

Cement plugs to be set @: 700-800' with 20 sacks
225-325' with 20 sacks

Hang 4 1/2" casing @ 200'; tack weld plate on top of 4 1/2" casing until pump is installed.

Surface will be restored as per USGS and BLM requirements.

MAY 24 1973

U. S. GEOLOGICAL SURVEY
DALLAS, TEXAS

18. I hereby certify that the above is true and correct

SIGNED

TITLE

DATE

5/18/73

APPROVED
CONDITIONS OF APPROVAL, IF ANY:

MAY 9 1973

JERRY W. LONG
DISTRICT ENGINEER

*See Instructions on Reverse Side