

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM 0556258

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Gulf Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Rusty Menefee

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 13, T22N, R7W

12. COUNTY OR PARISH

Sandoval

13. STATE

NM

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Chace Oil Company

3. ADDRESS OF OPERATOR

313 Washington, S.E., Albuquerque, N.M. 87108

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

Unit C 500 FNL, 1800 FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7022 GR

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐Progress Report ☒(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

4-3-75 Fluid level 1000' from surface. Sip 40# tubing-8:30 - Swabbed 24 bbls. fluid - rate of entry 1000' per hr.

4-4-75 Fluid level 1000# SIWHP 30# - 250' free oil on first swab - Rate of entry 300' per 15 min or about 6 bbls. per hr. Swabbing oil gas and water - 20% oil? Came out of hole - ran Halliburton Wire Line Bridge plug and set at 3925' (top of plug) 10:40 - Removed packer put on seating nipple and started back in hole. Tagged bridge plug with tubing pulled up 1 foot and started swabbing - First swab after being shut down approx. 3 bbls. oil little water - fire burned about 9 min. - continued swabbing - oil appears to be about 20% and improving. 1:30 - shut in for 15 min. for entry rate.

4-5-75 250' oil on top - fluid level 1000' 30# on top. Swabbed 44 bbls. fluid ran 18% oil - shut down to frac Monday.

4-6-75 Sunday - Shut down

18. I hereby certify that the foregoing is true and correct.

SIGNED

(This space for Federal or State office use)

TITLE

President

DATE 4-21-75

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side

