Form 3160-5 June 1990)	UNITED STATES  DEPARTMENT OF THE INTERIOR  BUREAU OF LAND MANAGEMENT		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
	BUREAU OF L	AND MANAGEMENT	5. Lease Designation and Serial No.
Do not use	this form for proposals to dri	AND REPORTS ON WELLS If or to deepen or reentry to a different reserve R PERMIT—" for such proposals	NM-0556258 6. If Indian, Allottee or Tribe Name
. Type of Well	SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
Oil Well Well Other  2. Name of Operator			8. Well Name and No.
HICKS OIL & GAS, INC.  3. Address and Telephone No.			Gulf Federal #1 9. API Well No.
P.O. Drawer 3307, Farmington, NM 87499 505-327-4902 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			300432015900S1 10. Field and Pool, or Exploratory Area
. Location of we	ar (Pootage, Sec., T., R., M., or Survey Des	cription)	Rusty Chacra
500' FNL & 1800' FWL Sec. 13-T22N-R7W			Sandoval County, NM
	ECK APPROPRIATE BOX(s) PE OF SUBMISSION	TO INDICATE NATURE OF NOTICE, REP	PORT, OR OTHER DATA
	PE OF SUBMISSION	TYPE OF ACTION	ON
L K	Subsequent Heart  MAR 2 5 1993	Abandonment  Recompletion  Plugging Back  Casing Repair	Change of Plans  New Construction  Non-Routine Fracturing
	Final Abandonment Notice	Altering Casing  Other	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on V
Describe Propose give subsurf	ed or Completed Operations (Clearly state all p face locations and measured and true vertical	ertinent details, and give pertinent dates, including estimated date of sta depths for all markers and zones pertinent to this work.)*	
	ject well was permanent		
3/18/93	Pumped 221 cf cement with no displacement.	$w/38$ l" ball sealers down $4\frac{1}{2}$ ", 10.	5# casing to 2041'
	Rusty Chacra Perforat	ions @ 1969'-73', 1982'-84' & 2039	'-41' w/2 spf.
	Let cement set & top	of cement was @ 195', filled casin	
	Erected dry hole mark	er.	RECEIVED BLM MAR 22 PM 1 FARMANGTON,
	Erected dry hole mark	Approved as to plugging of the wall to the Liability under band is assolved to all	ECEIVE BLM 22 PH
- //	4	Approved as to plugging of the well to be Liability under band is relatived until surface restarction to completed.	ECEIVED BLM 22 PH 1: 02
Signed	at the foregoing is true and correct	Approved as to plugging of the wall to the Liability under band is assolved to all	RECEIVED  AR 22 PM 1: 02  Date 3/19/93
(This space for F	,	Approved as to plugging of the world to Liability under bond is raisined until surface restaration is completed.  Tide President	22 PH : 02  Date 3/19/93
Signed	of the foregoing is tope and correct	Approved as to plugging of the well to be Liability under band is relatived until surface restarction to completed.	22 PH : 02  Date 3/19/93