

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved,  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR		8. FARM OR LEASE NAME	
FILON EXPLORATION CORPORATION c/o Minerals Management Inc.		Federal 29	
3. ADDRESS OF OPERATOR		9. WELL NO.	
501 Airport Dr., Suite 210, Farmington, New Mexico 87401		#1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT	
2080' FNL, 2310' FEL, SEC. 29, T21N, R7W		Wildcat	
14. PERMIT NO.		11. SEC., T., R., M., OR B.E. AND SURVEY OR AREA	
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH	
6834 KB		SEC. 29, T21N, R7W	
		13. STATE	
		Sandoval N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Operator proposes to PXA well as follows:

Plug #1	5993'-6143'	(150')	75 sacks
Plug #2	4968'-5118'	(150')	75 sacks
Plug #3	2901'-3051'	(150')	75 sacks
Plug #4	872'-1022'	(150')	75 sacks
Plug #5	182'-232'	(50')	35 sacks
Plug #6	0'-30'	(30')	15 sacks

**CONFIDENTIAL**

Verbal approval to PXA to J. Arnold Snell from Jerry Long 9-16-75

NOTE: THIS WELL IS STILL A TIGHT HOLE

18. I hereby certify that the foregoing is true and correct  
SIGNED J. Arnold Snell TITLE Area Manager  
Minerals Management Inc. DATE 9-17-75

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: