

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Dry Hole	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Filon Exploration Corporation	8. FARM OR LEASE NAME Federal 29
3. ADDRESS OF OPERATOR c/o Minerals Management Inc. 501 Airport Drive, Suite 210, Farmington, New Mexico 87401	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT Wildcat
1020C' FNL, 2310' FEL Sec. 29 T21N R7W	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 29 T21N R7W
14. PERMIT NO.	12. COUNTY OR PARISH Sandoval
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6834 KB	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well was Plugged and Abandon as follows:

Plug #1 6143'-5993' (150') 75 sx
Plug #2 5118'-4968' (150') 75 sx
Plug #3 3051'-2901' (150') 75 sx
Plug #4 1022'- 872' (150') 75 sx
Plug #5 232'- 182' (50') 35 sx
Plug #6 30'- 0' (30') 15 sx

CONFIDENTIAL

Dry hole marker erected. Location cleaned up, but has not been reseeded.



18. I hereby certify that the foregoing is true and correct

SIGNED

J. Arnold Sull

TITLE

Area Manager

Minerals Management Inc.

DATE 11-18-75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side