

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-7005

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 3

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

SEC. 3, T21N, R6W

12. COUNTY OR PARISH 13. STATE

Sandoval

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☐ GAS ☐  
WELL WELL OTHER Dry Hole

2. NAME OF OPERATOR

Dome Petroleum Corporation

3. ADDRESS OF OPERATOR c/o Minerals Management Inc.

501 Airport Dr., Suite 105, Farmington, N.M. 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface

660' FSL, 2310' FWL, SEC. 3, T21N, R6W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6891' GR 6903' KB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

1-4-77

Operator proposes to abandon well as follows:

Plug No. 1 6540'-6690' (150') 75 sacks (Top Entrada)  
Plug No. 2 5519'-5669' (150') 75 sacks (Top Dakota)  
Plug No. 3 3495'-3645' (150') 75 sacks (Top Mancos)  
Plug No. 4 1420'-1570' (150') 75 sacks (Top Chacra)  
Plug No. 5 143'-243' (100') 50 sacks (Base Surface Pipe)  
Plug No. 6 0'-30' (30') 15 sacks (Surface)

Dry hole marker will be erected.

Oral approval to abandon from Mr. Ed Schmidt-U.S.G.S.-Durango, Colo.  
on January 4, 1977.

18. I hereby certify that the foregoing is true and correct.

SIGNED J. Charles Swell

Area Manager

TITLE Minerals Management Inc. DATE 1-5-77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

