

✓

**RIJAN OIL COMPANY, INC.**

20 FIRST PLAZA, SUITE 402  
ALBUQUERQUE, NEW MEXICO 87102  
(505) 243-0665

June 17, 1977

Mr. A. R. Kendrick, District Supervisor  
Oil Conservation Commission  
1000 Rio Brazos Road  
Aztec, New Mexico 87410

*L-23-19-3*

Deviation Letter  
Rijan Oil Company, Inc.  
No. 1 PLR, Inc. well


Dear Sir:

The Rijan Oil Company, Inc. No. 1 PLR, Inc. well is located 1650' from the south line and 760' from the west line in Section 23, Township 19 North, Range 3 West, N.M.P.M., Sandoval County, New Mexico.

This well was drilled to a total depth of 3250' and the following vertical deviations (Totco surveys) were taken from the drilling log:

505'	$3/4^{\circ}$
1947'	$1/2^{\circ}$
2610'	$1/2^{\circ}$
3050'	$3/4^{\circ}$
3250'	$1/2^{\circ}$

I certify that the above surveys are true and correct information obtained in regard to the vertical hole deviations on the No. 1 PLR, Inc. well.



Val R. Reese, Geologist

State of New Mexico :  
County of Bernalillo :

Subscribed and sworn to before me this 17th day of June, 1977.

*Marilyn Bunting*  
Notary Public

My commission expires 9-25-77.