Drawer 600 Farmington, New Maxico 87401

November 24, 1981

Rijan Oil Company, Inc. 20 First Plaza, Suite 402 Albuquerque, New Mexico 87102

Gentlemen:

This is in response to your letter dated March 12, 1981, concerning land rehabilitation following the PGA of your well No. 1 PLR Inc., SWISW's sec. 23, T. 19 N., R. 3 W., located on Pederal lease No. NM-26655, Sandoval County, New Mexico. It is unknown at this time whether any additional land rehabilitation will be required or not. However, we are not allowed to approve a subsequent report of PGA and land rehabilitation until the site has been inspected by the surface management agency (in this case the BIM) and the rehabilitation has been approved by them.

The BIM has been notified of the abandonment of this well and we are awaiting their reply regarding the adequacy of the land rehabilitation. As soon as we hear from them, we will either approve and distribute your subsequent notice or notify you of any additional rehabilitation that may be required.

Sincerely yours,

(Orig. Sed.) RAYMOND W. VINYARD

Raymond W. Vinyard Acting District Oil and Gas Supervisor .

cc: SCR NMOCC Aztec