

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

(Other instructions on reverse side)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☐ GAS WELL ☒ OTHER

NAME OF OPERATOR

Dome Petroleum Corporation

ADDRESS OF OPERATOR Minerals Management Incorporated

501 Airport Drive, Farmington, New Mexico 87401

LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

1040' FNL & 1190' FEL

4. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6802 GR

6. LEASE DESIGNATION AND SERIAL NO.
NM-6680

8. IF INDIAN, ALIQUOT OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Navajo 21

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT

Rusty Chacra Extension

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 21, T22N, R7W

12. COUNTY OR PARISH 13. STATE

Sandoval N.M.

6. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) Change of Operator ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐


(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Dome Petroleum Corporation is now the operator of this lease formerly operated by Kirby Exploration Company, P. O. Box 1745, Houston, Texas 77001.

The thirteen-point development plan remains intact except that point 12 should be changed to contact W. E. Landry, Minerals Management Inc., 501 Airport Drive, Farmington, New Mexico, 87401. Telephone 505-327-4441.

unspud loc



8. I hereby certify that the foregoing is true and correct

SIGNED W. E. Landry

TITLE Area Manager

DATE 3-2-78

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

OK

*See Instructions on Reverse Side