Form	9-331	
(Mav	1963	١

1.

UNITED STATES DEPARTMENT OF THE INTERIOR vers GEOLOGICAL SURVEY

BMIT IN TRIPLICATE.	
her instructions on re-	Budget Buleau
e side)	5. LEASE DESIGNATION AT

r IN TRIPLICATE.	Budget Bureau No. 42-R1424				
de)	5. LEASE DESIGNATION AND SERIAL NO	•			

CHADRY	NOTICES	AND	REPORTS	ON	WFII	ς

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.)

Jicarilla

8. FARM OR LEASE NAME

Contract 428

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

	 			 	 	 7.	UNIT AGREEMENT	I A
OIL	GAS	$[\mathbf{x}]$	OTHER	•				

2. NAME OF OPERATOR J. Gregory Merrion and Robert L. Bayless

Jicarilla 428 9. WELL NO. 3. ADDRESS OF OPERATOR

P.O. Box 507, Farmington, NM 87401

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface 10. FIELD AND POOL, OR WILDCAT

790 FSL and 1170 FWL

Ballard Pic. Cliffs 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 30, T23N, R4W 12. COUNTY OR PARISH | 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 6884' GL Sandoval N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
EST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL		
FRACTURE TREAT		MULTIPLE COMPLETE	.	FRACTURE TREATMENT	ALTERING CASING		
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING	ABANDONMENT*		
EPAIR WELL		CHANGE PLANS		(Other) Perforate,		X	
Other)				(Note: Report results of Completion or Recomple	of multiple completion on Well tion Report and Log form.)		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Pulled slips from wellhead, tightened 2-7/8" casing, Rig up Flint Rig. 04 - 13 - 78and reset in slips. Rigged down.

Rig up Blue Jet, ran Gamma Ray Collar Log. Perforated 2165-88' with 04 - 19 - 7818 holes, 2159-61' with 3 holes. Western Company acidized with 1000 gallons 15% HCL. Shut in awaiting frac.

Rig up Western and fraced with 830 Bbls. slick water and 47,600 lbs. 04 - 24 - 7810/20 sand. ISDP 500 PSIG. Shut in three hours and opened to flow back.

18. I hereby cartify that the foregoing is true and correct 05-12-78 Co-Owner SIGNED (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

MAY 1 5 1978