



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Jennifer A. Salisbury
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

June 6, 2001

John Roe
Dugan Production Corp
PO Box 420
Farmington NM 87499-22175

Re: Dome Rusty 30-22-6 #1, B-30-22N-06W API 30-043-20318

Dear Mr. Roe:

The Bradenhead test report on the above well indicates no Bradenhead valve was located. Review Rule 115.B. "Valves shall be installed and maintained in good working order to permit pressures to be obtained on both casing and tubing..." you are hereby directed to bring this well into compliance before August 15, 2001

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely,

Charlie T Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC:

BLM Farmington
CTP
Well File