



ENERGY AND MINERALS DEPARTMENT  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

JERRY APODACA  
GOVERNOR

NICK FRANKLIN  
SECRETARY

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

August 23, 1978

Mr. Jerome B. Weber  
Helton Engineering & Geological Services, Inc.  
860 Anaconda Tower  
555 Seventeenth Street  
Denver, Colorado 80202

Re: Brent #1, M-29-13N-6E  
Brent #3, G-19-13N-6E

Dear Mr. Weber:

I have your requests for approval of forms C-103 for the subject wells as Subsequent Report of Abandonment.

I have been studying the plugging reports and find that neither of the wells has been plugged in a satisfactory manner.

The enclosed copies of well logs identify zones where cement will have to be placed to obtain plugging approval.

Additional plugging will be as follows:

Brent #1:

1. Tag top of cement plug at 1600'.
2. Set cement plug 1600' to 1540'.
3. Set a cement plug from 550' to 350'.
4. Set a cement plug from 170' to 130'.
5. Set marker.
6. Clean and level location.

Brent #3:

1. Tag cement top at 1937'.
2. Set cement plug from 1937' to 1810'.
3. Set a cement plug from 1100' to 830'.
4. Set a cement plug from 220' to 120'.
5. Set marker.
6. Clean and level the location.

Advise this office 48 hours in advance of the reentry of these wells so that we may provide a witness at our option.

Mr. Jerome B. Weber  
August 23, 1978  
Page 2

All future abandonment programs shall be approved prior to abandonment. None will be approved prior to knowing the formation tops.

If there are questions, please contact this office.

Yours very truly,



A. R. Kendrick  
District Supervisor

enclosures

ARK:no