State of New Mexico Form C-103 Submit 3 Copies 3 NMOCD 1 Files, Minerals and Natural Resources Department Revised 1-1-89 to Appropriate District Office OIL CONSERVATION DIVISION DISTRICT WELL API NO. P.O. Box 1980, Hobbs, NM \$2240 P.O. Box 2088 Santa Fe, New Mexico 87504-2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 LG 3923 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) State 32-22-6 Type of Well: WELL X WEIL 2. Name of Operator & Well Na. DUGAN PRODUCTION CORP 9. Pool name or Wildcat 3. Address of Operator Rusty Chacra P.O. Box 420, Farmington, NM 87499 Well Location 1010 Feet From The West Line Unit Letter D: 1100 Feet From The North _ Line and _ County 6W Sandova1 Township 22N Range 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDONMENT X COMMENCE DRILLING OPNS. CHANGE PLANS **TEMPORARILY ABANDON** CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER:_ OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Plan to replace tubing and attempt to return well to production. If unsuccessful, will plug and abandon. SIONATURE TYPE OR PRINT NAME JUN 3 0 1992 (This space for State Use) DEFLITY OH & GAS UNSPECTOR, DIST. #3 Original Signed by CHARLES GHOLSON APPROVED BY-

CONDITIONS OF APPROVAL, IF ANT: