		•		/
UNITED STATES SUBMIT IN TRIPLICATE* Other instructions on responded to the state of the state				
	ORY NOTICES AND Form for proposals to drill or to use "APPLICATION FOR PERM			6. IF INDIAN, ALLOTTEE OR TRIBE NAME
I. OIL X GAS WELL OTHER				7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Hanson Oil Corporation				S. FARM OR LEASE NAME Candy Butte
P. O. Box 1515, Roswell, New Mexico 88201 4. Location of well (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface				9. WELL NO. #3 10. FIELD AND POOL, OR WILDCAT Wildcat 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
660' FNL & 660' FWL				Sec. 8, T.17N, R.2W
14. PERMIT NO.		Show whether DF, F	rr, GR, etc.)	Sandoval New Mexic
16.	Check Appropriate Box	To Indicate Na		
N	OTICE OF INTENTION TO:	()]	SUBS	EQUENT REPORT OF:
TEST WATER SHUT-OF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	PULL OR ALTER CAS MULTIPLE COMPLET ABANDON® CHANGE PLANS		(Note: Report rest	ABANDONMENT* Det Conductor Pipe Alts of multiple completion on Well mpletion Report and Log form.)
Spud well	on 11-16-79. Drill	and set 20)' of 16" conducto	r pipe.
				JAN 1 8 1980 OIL CON. C DIST. 3
200	the foregoing is true and correct	Pro Pro	oduction Clerk	DATE 1-7-80
(This space for Feder	ral or State office use)	TITLE		
ACCEPTED FOR R	ECORD	TITLE		JAN 11 1090
CONDITIONS OF AP	PROVAL, IF ANY:			DES GEOLOGISZE SURVAY

.M17'80

State

*See Instructions on Reverse Side

U. S. GEOLOGICAL SULVAY