

Multi-Point Surface Use Plan

Federal #12

1170' fwl & 2230' fsl Sec 29 T17N-R4W

Sandoval County, New Mexico

- 1) The attached topo map shows the existing route to the location and distance from Torreon Trading Post
- 2) No access roads will be constructed
- 3) No existing oil or gas wells exist within a one-mile radius from the proposed location
- 4) There are no existing storage tanks or facilities located within a one-mile radius from the proposed location
- 5) No water will be required for drilling
- 6) No construction materials will be required for this location
- 7) No pits will be required for this location
- 8) There are neither airstrips nor camps in the vicinity
- 9) The well site is shown on the attached map
- 10) Restoration will be accomplished by cleaning up. Reseeding of the site will be carried out as detailed by the Surface Management.
- 11) The general topography consists of fairly level terrain and vegetation consists of sagebrush & juniper. Representatives of the U.S. Geol. Survey, Cultural resources inspection has been conducted by Leroy Herwitz, archaeologist from Salmon runs and the surface has been examined by BLM, Albuquerque